Drig 10345

STATE UNIVERSITY COLLEGE AT OSWEGO, NY ELEVATOR STUDY



HYDRAULIC ELEVATORS
UPGRADE STUDY
JUNE 20, 2008

TABLE OF CONTENTS

SECTION

A.	EXECUTIVE SUMMARY:	5
B.	REPORT DESCRIPTION:	5
C.	EQUIPMENT OVERVIEW:	5
D.	OPINION OF PROBABLE COST	
1.	ELEVATOR #1 SHELDON HALL	9
	1.1. EXISTING COMPONENT SUMMARY AND UPGRADERECOMMENDATIONS:	
	1.2. PHOTOS:	11
	1.3 SUMMARY OF ANCILLARY SYSTEM UPGRADES:	15
	1.4. OPINION OF PROBABLE COST ELEVATOR #1 SHELDON HALL:	18
	1.5. EQUIPMENT INVENTORY ELEVATOR #1 SHELDON HALL:	18
	1.6. APPENDIX 3: QEI INSPECTION REPORTS	19
	1.7. ELEVATOR MAINTENANCE REPORT -ELEVATOR #1 SHELDON HA	
2.	ELEVATOR #2 LANIGAN HALL	23
	2.1. EXISTING COMPONENT SUMMARY AND UPGRADERECOMMENDATIONS:	23 23
	2.2 PHOTOS:	25
	2.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:	28
	2.4. OPINION OF PROBABLE COST ELEVATOR #2 LANIGAN HALL:	30
	2.5. EQUIPMENT INVENTORY ELEVATOR #2 LANIGAN HALL:	30
	2.6. APPENDIX 3: QEI INSPECTION REPORTS	31
	2.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #2 LANIGAN HA	



Oswego College Elevator Upgrade Study #003291G

3.	ELEVATOR #3 PENFIELD LIBRARY	35
	3.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:	
	3.2. PHOTOS:	37
	3.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:	41
	3.4. OPINION OF PROBABLE COST ELEVATOR #3 PENFIELD:	43
	3.5. EQUIPMENT INVENTORY ELEVATOR #3 PENFIELD:	43
	3.6. APPENDIX 3: QEI INSPECTION REPORTS	44
	3.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #3 PENFIELD LIBRARY:	47
4.	ELEVATOR #4 COOPER DINING HALL	48
	4.1. EXISTING COMPONENT SUMMARY AND UPGRADE	
	4.2. PHOTOS:	50
	4.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:	54
	4.4. OPINION OF PROBABLE COST ELEVATOR #4 COOPER:	56
	4.5. EQUIPMENT INVENTORY ELEVATOR #4 COOPER:	56
	4.6. APPENDIX 3: QEI INSPECTION REPORTS	57
	4.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #4 COOPER:	60
5A.	ELEVATOR #5A HEWITT (PASSENGER)	61
	5a.1 EXISTING COMPONENT SUMMARY AND UPGRADE	61 61
	5A.2. PHOTOS - ELEVATOR #5A:	63
	5A.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES-ELEVATOR #5A	: 67
	5A.4. OPINION OF PROBABLE COST ELEVATOR #5A HEWITT:	69
	5A.5. EQUIPMENT INVENTORY ELEVATOR #5A HEWITT:	69
	5A.6. APPENDIX 3: QEI INSPECTION REPORTS	70
	54.7 FLEVATOR MAINTENANCE REPORT - ELEVATOR #54 HEWITT	73



Oswego College Elevator Upgrade Study #003291G

5B.	ELEVATOR #5B HEWITT (SERVICE CAR)	74
	5B.1. EXISTING COMPONENT SUMMARY AND UPGRADE	
	5B.2. PHOTOS - ELEVATOR #5B:	76
	5B.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES-ELEVATOR #5B	: 79
	5B.4 OPINION OF PROBABLE COST ELEVATOR #5B HEWITT:	8เ
	5B.5. EQUIPMENT INVENTORY ELEVATOR #5B HEWITT:	81
	5B.6. APPENDIX 3: QEI INSPECTION REPORTS	82
	5B.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #5B HEWITT	85
6.	ELEVATOR #6 TYLER ARTS	86
	6.1. EXISTING COMPONENT SUMMARY AND UPGRADE	
	6.2. PHOTOS:	88
	6.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:	94
	6.4. OPINION OF PROBABLE COST ELEVATOR #6 TYLER:	96
	6.5. EQUIPMENT INVENTORY ELEVATOR #6 TYLER:	96
	6.6. APPENDIX 3: QEI INSPECTION REPORTS	97
	6.7 FLEVATOR MAINTENANCE REPORT - ELEVATOR #6 TYLER:	100



EXECUTIVE SUMMARY:

B. REPORT DESCRIPTION:

CNY Elevator Consultants, LLC (CNYEC) is pleased to provide you with this study for 7 hydraulic elevators located in the State University of New York at Oswego College in Oswego, NY. This evaluation report is based on CNY's field inventory and QEI-1 certified elevator inspection on June 3, 2008. The evaluation contained herein is specific to the locations indicated only and is not intended to be a substitute for required testing, maintenance, or qualified design of new or existing materials, methods, or systems.

C. EQUIPMENT OVERVIEW:

Elevator # Key: Elevator #1 Sheldon Hall, Elevator #2 Lanigan Hall, Elevator #3 Penfield Library, Elevator #4 Cooper Dining Hall, Elevator #5A Hewitt (Passenger), Elevator #5B Hewitt (Service Car), Elevator #6 Tyler.

CNYEC has reviewed the available documentation and evaluated the existing conditions at the site and found the existing seven elevators in service to be in poor condition. Maintenance condition was above average. Based on their current use it is our opinion that all seven elevators should be modernized sooner than later. These elevators are heavily used, therefore a long term shutdown would cause a significant burden on the building occupants. It is recommended that the Owner begin an upgrade program to modernize all seven elevators.

Prior to 1972 elevator hydraulic cylinders were installed with a single bottom end cap which contained the oil at the bottom of the cylinder. Elevators # 2, 3, 4, 5A, 5B and 6 were installed in the mid-1960's. CNY has contacted the original equipment manufacturers at Dover (now Thyssen-Krupp Elevator Co.) and Otis Elevator Co. and both manufacturers have confirmed that they had installed exclusively single bottom end cap cylinders in the mid 1960s. Based on the available documentation, CNY is confident that the cylinders of elevators 2-6 are single bottom cylinders.

In the early 1970's the elevator industry recognized that a single bottom cylinder end cap could cause a catastrophic failure if the cap were to fail due to corrosion (called electrolysis). Unlike roped elevators, hydraulic elevators do not have safety mechanisms that prevent the elevator from falling, so the loss of a bottom end cap would cause the elevator to fall at the rate that the hydraulic fluid is displaced potentially causing a catastrophic failure. In the U.S. in 1971 and Canada in 1977 the elevator code was changed to require that a second end cap be added to the cylinder bottom, commonly called a "safety bulk head" or "double-bottom cylinder." A safety orifice was installed below the original end cap to allow a slow loss of oil in the event of failure of the new bottom end cap.

That type of construction was installed widely in the US and Canada until 2000 when additional requirements were added that included protecting the entire cylinder from corrosion. The 2000 elevator code, adopted in New York Sate on January 1, 2003 required that all new hydraulic pistons be provided with cylinder corrosion protection and a means to monitor that protection for integrity. Since 2003 all hydraulic elevators in NYS have been installed with new cylinders in PVC liners



which are intended to prevent corrosion. The adoption of the 2000 elevator code also included the provision to verify maintenance of existing cylinders installed prior to 2003 and a requirement to have a written record of oil usage in the machineroom to assure that inground cylinders were not subject to cylinder failure or leakage due to corrosion.

The New York State Department of State Codes Division subsequently determined that the requirement to verify the integrity of existing inground cylinders was not enforceable under the New York State Constitution. However, it should be understood that the requirement of the Owner to maintain the hydraulic cylinder in a manner consistent with protection of the public from a catastrophic failure is still enforceable under the Property Maintenance Code as well as civil liability. A catastrophic failure of a single bottom cylinder in Toronto on January 27, 2006 injuring 5 people greatly increased the concern nationwide about the need to replace existing single bottom cylinders which are more than 35 years old. Additionally, increased scrutiny of environmental concerns with the loss of oil from leaking underground cylinders has accelerated the push in North America to replace the older cylinders with the new PVC contained cylinder systems.

Based on our own QEI-1 certified periodic inspection it appears that the existing cylinders have not had the State required witnessing of the elevator's annual safety tests. Although it does appear that the maintenance contractor, based on their own maintenance records, has been performing pressure tests on relief valves, it is not clear that the tests included verification of the cylinder integrity. It is strongly recommended that the annual tests be completed and witnessed by an independent QEI certified elevator inspector sooner than later. In the event of future catastrophic failure, the Owner would likely be expected to provide proof that the New York State code requirements for certified inspection and testing had been met, and the tests had been independently verified.

We found most of the remaining components to be in poor but typical condition based on age. Building occupants indicated to CNY that there was a history of problems which is consistent with our field inventory and maintenance reports indicating that the useable life of the controllers, door operators, and support mechanisms were significantly beyond their expected life-span. The existing controllers, intended for about a 20 year lifespan, are now more than 40 years old. Maintenance of equipment this old is difficult and ultimately leads to increased failures and costs. It should be noted that it is not required by building code to replace the controllers as part of the upgrade to the cylinders, however it may be in the Owner's best interest to complete the operational upgrades while the elevators are out of service for the cylinder replacements.

Elevators 3, 4, 5A, 5B, and 6 currently do not meet the standards for Accessibility. It is recommended that any upgrade to the controller equipment include compliance with regulations for barrier free access including call station fixtures, visual and audible signals, and floor leveling.

Elevators 3, 4, 5A, 5B, and 6 do not have fire service functionality. Following several multiple loss of life fires in the early 1970s the elevator codes were changed to improve life safety for the elevator riding public in the event of fire. Any upgrade to the elevator controllers should include the addition of fire service phase one and phase two functionality to protect the public from the dangers which elevators present during a building fire. None of the elevators 1-6 have fire service which meets the current standards for new construction.



In all cases the Cabs were found to be in good to fair condition. Modest improvements to their appearance as part of the upgrade to the car operating panel upgrades could be added at the Owner's discretion.

An opinion of probable cost for elevator work only is provided at the end of each individual study. A complete summary of probable costs and a proposed capital improvement program for the seven elevators included in this study is provided in Part D of this report.

D. OPINION OF PROBABLE COST:

An individual Opinion of Probable Cost for each elevator is provided in each section of this report. Following is a summary of those opinions:

Opinion of Probable Cost for year 2009 construction

Elevator Work Only: \$715,104

Cylinders Only: \$198,400 All work: \$913,504


Opinion of Probable Cost for year 2010 construction

Elevator Work Only: \$438,697

Cylinders Only: \$99,200 All work: \$537,897

Total: \$1,451,401





Suth 305 126 North Soling Sheet Syrocose, NY 12302 Tel (315) 425-0428 Fox (315) 425-1232

STATE UNIVERSITY OF NEW YORK AT OSWEGO HYDRAULIC ELEVATOR STUDY

TOTAL ALL ELEVATOR WORK =

OP COST FOR ALL ELEVATOR WORK (INCLUDES CYLINDERS): 2009 OP COST ESTIMATE ALL ELEVATOR WORK = 2010 OP COST ESTIMATE ALL ELEVATOR WORK =

- 1. ELEVATOR #1 SHELDON HALL
- 1.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:
 - 1.1.1. CONTROLLER: The existing Midstate Elevator microprocessor/ice-cube relay based elevator controllers was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1987 by Midstate Elevator Company which is no longer in business. The existing microprocessor is difficult to maintain and can fail completely by losing its flash-type memory. It is possible to back up the existing memory to prevent the loss of the entire memory, however finding a qualified individual familiar with Midstate equipment is becoming increasingly difficult. The design of this equipment even new had limited technical support, and that situation is significantly worse now. The controller should be upgraded sooner than later.
 - 1.1.1.1. A 20-year life span for a controller is typical both in terms of the expected lifespan of the specific components but also as it relates to providing optimum efficiency with new technologies. The Midstate controller has reached that age and added to the fact that the manufacturer is no longer in business emphasizes our recommendation to upgrade the controller sooner than later.
 - 1.1.1.2. Its current location is not code compliant. It's location near an open water drain is a potential shock hazard and the surrounding moisture adds to its wear and unreliability. It is recommended that the location of the controller be changed at the time of controller upgrade.
 - 1.1.2. HOISTING COMPONENTS: The existing 40-HP submersible motor, valve, and hydraulic reservoir can likely be retained however they should be relocated as part of the controller relocation. The existing inground cylinder appears to be in good condition. Because the cylinder was installed after 1972, it is expected to have a double-bottom cylinder and can likely be retained. However the cylinder was not installed in a PVC jacket which would allow the cylinder integrity to be constantly monitored for corrosion and leaks. A QEI certified witnessing of the cylinder pressure test to verify its integrity should be completed as soon as possible.
 - 1.1.3. DOORS: Front and Rear Door operation.
 - 1.1.3.1. The existing light ray and safety edge (boot) type door detection should be upgraded with infrared type door detectors as part of the controller upgrade.



- 1.1.3.2. The existing GAL door operators are in fair condition but should be upgraded as part of the elevator controller upgrade.
- 1.1.3.3. Door restrictors are currently required, however they were not functioning at the time of CNY's inventory.
- 1.1.3.4. It is unlikely that the existing hoistway doors contain ACBM and they can likely be retained.
- 1.1.3.5. The existing hoistway door tracks can likely be retained if the hoistway doors are retained. The existing hoistway door rollers and gibs should be replaced at the time of controller upgrade.
- 1.1.3.6. The GAL interlocks appear to be in good condition and can likely be retained.
- 1.1.3.7. The existing car doors are in fair condition and can likely be retained.
- 1.1.4. <u>CALL STATIONS</u>: The existing hall call stations in the lobbies appear to conform to current ADA standards. The hall call stations appear to be in good condition and well maintained. The recall key station will require modest modification at the time of elevator controller upgrade.
 - 1.1.4.1. The car operating panel will require replacement at the time of the controller upgrade to comply with current elevator codes for fire service.

1.1.5. CAB:

- 1.1.5.1. The cab was found to be in good condition and likely be retained.
- 1.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the renovation.

1.1.6. ADDITIONAL COMPONENT SUMMARY:

- 1.1.6.1. The elevator pit is required to have a pit ladder installed.
- 1.1.6.2. The existing machineroom does not comply with the current elevator code requirements for ventilation, lighting and head clearance. A review of options to relocate the elevator equipment to a new space is recommended. It is unlikely that the existing room would be granted a code variance to permit retention of equipment in the existing space.



1.1.6.3. The existing pit switch is worn and should be replaced at the time of controller upgrade.

1.2. PHOTOS:



Main Lobby Floor Landing

Oswego College Elevator Upgrade Study #003291G



Existing Machineroom



Machineroom and Existing Controller



Oswego College Elevator Upgrade Study #003291G



Bottom of Car and Existing Piston



Existing Pit





Top of Car and Exist Door Operator

1.3 SUMMARY OF ANCILLARY SYSTEM UPGRADES:

1.3.1. ELECTRICAL:

- 1.3.1.1. The existing disconnecting means does not have a grounded connection back to the building ground. Any renovation including a new controller will require installation of a properly grounded connection. If the machineroom is provided with sprinklers as part of the renovation project, a new shunt trip breaker would be required.
- 1.3.1.2. The existing cab lighting and fan disconnect could not be tested because their location was not readily apparent. In the event of a modernization, a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible, the cab lighting and fan should be connected to an emergency generator.
- 1.3.1.3. The existing machineroom lighting is required to be protected against breakage. A new machineroom GFCI protected convenience outlet is required at the time of controller upgrade.
- 1.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of controller upgrade.

1.3.2. FIRE ALARM:

- 1.3.2.1. Annual testing of the integrated Fire Alarm/Ventilation/and Elevator recall circuits and devices is recommended.
- 1.3.2.2. At the time of the next elevator controller upgrade, it will be necessary to provide the fireman's flashing hat signal to the elevator car from any FAID located in the machineroom or hoistway.

1.3.3. HVAC:

1.3.3.1. The existing machineroom does not comply with the current elevator code requirements for ventilation. A review of options to relocate the elevator equipment to a new space is recommended.



- 1.3.3.2. The existing hoistway vent may not be currently operable. It is recommended that the hoistway vent be tested for proper operation. Unless the building is fully sprinklered, a vent in the shaft for this current occupancy is required.
- 1.3.3.3. Machineroom ventilation should include smoke and heat dampers to protect openings in the event of fire. A review of the cooling requirements during the summer months is recommended to verify that adequate fresh air can be provided.

1.3.4. COMMUNICATIONS:

1.3.4.1. The existing emergency telephone in the car was working properly at the time of inspection.

1.3.5. PLUMBING:

1.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.

1.3.6. GENERAL CONSTRUCTION:

- 1.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals. The existing hoistway does have some issues with the fire resistance that should be addressed sooner than later.
- 1.3.6.2. The existing machineroom cannot be made to comply with current elevator codes for clearances and access. It is recommended that alternate locations be considered. It is not likely that a code variance would be granted to allow the existing machineroom to be maintained as part of a renovation.



1.3.7. FIRE PROTECTION:

- 1.3.7.1. The existing elevator machineroom does not have sprinklers, however there is a sprinkler in the hoistway. At the time of the controller upgrade the sprinkler would be required to be removed or a new shunt trip type main line disconnecting means would be required to be integrated into the sprinkler and fire alarm system.
- 1.3.7.2. The existing smoke detector in the hoistway is required if the sprinkler remains in the hoistway or if there is a hoistway vent to be operated by a smoke detector.
- 1.3.7.3. An ABC-type fire extinguisher is required to be located in the machineroom.



1.4. OPINION OF PROBABLE COST ELEVATOR #1 SHELDON HALL:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2010.

Elevator Controller, Door Operators and Infrared detectors: \$60,000-\$72,000

Total for all elevator work: \$78,000

1.5. EQUIPMENT INVENTORY ELEVATOR #1 SHELDON HALL:

Year of Construction: 1987 Manufacturer: Midstate Type: Passenger

Capacity: 3000 Lbs.

150 FPM (Measured speed NL: 150FPM/up 128FPM/dn)

4 stop: L= Front, 1=Rear, 2=Rear 3=Rear

Fire Service PH 1 & 2 Recall Level: L

Hoisting Type: Direct Acting Inground Cylinder (no PVC)

HP: 40 Submersible WP= 380 RP= 470 208V/3PH/ 4-wire Maxton valve

Emergency Power: None Last Test: 8/07, QEI: No

Doors:

Center Opening: 42" (F & R)

Operator: GAL

Protection: Light-ray/ Safety edge

ADA: Yes

Fixtures: Innovation

Phone: Yes

Cab Dimensions: 6'-8"W x 5'-0"D x 8'-0"H (Drop ceiling at 7'-6")

Finish: Steel with PVC laminate application



1.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fox (315) 425-1232 inspections cnyei.com

Sheldon Hall Oswego University Oswego, NY Owner: Oswego State University of New York Type Passenger Rated Load 3000 Year Constructed 1987 Manufacturer Midstate

Date of Inspection	6/3/2008
Inspector	Chris Duke
QEI Certification #	S-111
QEI Cert. Issuer	NAESA International
Workorder Designator	080604-00-04D1-I
Authoritative Jurisdiction	State University of New York

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason				
Operating control devices	Item 1.3	Both Directional Indicators did not function				
Car lighting and receptacles	Item 1.5	Emergency lighting could not be checked (power source location unknown)				
Restricted opening of car/hoistway doors	Item 1.18	The car and hoistway door must meet the restricted opening requirements when the car is more than 18 inches above or below the landing (front door)				
Access to machine space	Item 2.1	Machine room door must be self closing and self locking (Can not unlock door handle from inside machine room)				
Headroom	Item 2.2	Machine room or control room does not have minimum overhead clearance				
Lighting and receptacles	Item 2.3	Machine room lighting not protected				
Machine space	Item 2.4	Machine space appears to have water leaks				
Fire Extinguisher	Item 2.7	ABC type fire extinguisher required to be provided in a location convenient to the machine room access door				
Disconnecting means and control	Item 2.11	Provide source grounding in power machine room disconnect				
Relief valves	Item 2.31	QEI witnessing of annual tests required				
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection				
Pit access lighting, stop switch and condition	Item 5.1	Pit Ladder Required				
Fire Service Operation (89-00 ed)	Item 6.4	Provide Phase 1 instructions				



Inspector's Signature

Sheldon Hall	Page	2		
Oswego University	Date of Inspection	6/3/2008		
Oswego, NY 00000	Inspector	Chris Duke		
Owner: Oswego State University of New York	Workorder Designator	080604-00-04D1-I		

		_			11.01	order Designator 1080604-00-04			
	Checklist for Hydro				or - P	eriodic Inspection Report	245	1000	
Interio	or of Car	OK	NG	NA	3.9	Floor and emergency identification numbering	OK X	NG	NA
1.1	Door reopening device	X			3.10	Hoistway construction		H	H
1.2	Stop switches	X	Ħ	Ħ	3.11	Hoistway smoke control		H	
1.3	Operating control devices	×	×	П	3.12	Pipes wiring, and ducts	X	H	
1.4	Sills and car floor	X		一	3.13	Windows, projections, recesses, and setbacks			H
1.5	Car lighting and receptacles	Ē	X	П	3.14	Hoistway clearances	X	Ħ	H
1.6	Car Emergency signal	X		\Box	3.15	Multiple hoistways	П	Ħ	X
1.7	Car door/gate				3.16	Traveling cables and junction boxes			
1.8	Door closing force	X			3.17	Door and gate equipment	X		
1.9	Power closing of doors/gates			X X	3.18	Car frame and stiles	X		
1.10	Power opening of doors/gates			X	3.19	Guide rails fastening and equipment	X		X X X X
1,11	Car vision panels and glass car doors			X	3.20	Governor rope			X
1.12	Car enclosure	XXXXX			3.21	Governor releasing carrier			X
1.13	Emergency exit	X		Ц	3.22	Wire rope fastening and hitch plate			X
1.14	Ventilation	M			3.23	Suspension rope	\Box		X
1.15	Signs and operating device symbols	X		님	3.30	Speed test			X
1.16	Rated load, platform area and data plate	ᅜ	님		3.31	Slack rope device roped-hydraulic elv 1989 and later			X
1.17 1.18	Standby power operation	님	님	×	3.32	Traveling Sheave roped-hydraulic elv 1989			X
1.19	Restricted opening of car/hoistway doors Car ride	×				and later			
	ne Room		u		3.33	Counterweight			X
2.1	Access to machine space		N			łe Hoistway			
.2	Headroom	H	듬	H	4.1	Car platform guard	X		
2.3	Lighting and receptacles	\exists	띉	H	4.2	Hoistway doors	X		
.4	Machine space	Ħ	X	H	4.3	Vision Panels		Н	X
2.5	Housekeeping	X	X X X X	Ħ	4.4	Hoistway door locking devices	×	님	X U
2.6	Ventilation	NNUNN	Ħ	Ħ	4.5	Access to Hoistway	설	H	H
2.7	Fire Extinguisher	ī	×	П	4.6	Power closing of hoistway doors	Ä	H	
.8	Pipes, wiring, and ducts	X		\Box	4.7 4.8	Sequence operation	띉	H	H
2.9	Guarding of exposed auxilary equipment	X			4.9	Hoistway enclosure Elevator Parking devices	A	H	님
.10	Numbering of elevators, machines and disconnect switches	X			4.10	Emergency doors blind hoistway			X X
2.11	Disconnecting means and control		X		4.12	Standby power selection switch			X
2.12	Controller wiring, fuses grounding, etc.	X			Pit		_		_
2.13	Govenor, overspeed switch and seal			X	5.1	Pit access lighting, stop switch and condition	님	×	님
.14	Code data plate	X			5.2	Bottom clearance, runby and minimum refuge space	X		
2.30	Hydraulic Power Unit	X	X		5.3	Final and emergency terminal stopping	X		
2.31	Relief valves		×	\Box		devices			
2.32	Control valve		\vdash	님	5.4	Normal terminal stopping devices		Ц	
2.33	Tanks	Ä	\forall	님	5.5	Traveling cables	M	Ц	\vdash
.34	Flexible hydraulic hose and fitting assemblies	띉	H	님	5.6	Governor-rope tension devices	닞	H	X
.35	Supply Line and Shutoff Valve		\vdash	님	5.7	Car Frame and platform	×		
2.36	Hydraulic Cylinders Pressure Switch	씜	H	×	5.8	Car safeties and guiding members	님	H	M
2.38	Roped water hydraulic elevators	뭄	H	X	5.11	Plunger and cylinder	X		H
op of	The state of the s				5.12	Car buffer	X	H	H
3.1	Top-of-car stop switch	X			5.13 5.14	Guiding members		H	H
3.2	Car top light and outlet	XXXXXX	H	H		Supply piping phter's Service			
3.3	Top-of-car operating device	X	H	Ħ	6.1	Fire Service Operation (73-80 ed)			X
3.4	Top-of-car clearance and refuge space	X	Ħ	\Box	6.2	Fire Service Operation (93-83 ed)	H	Ħ	X
3.5	Normal terminal stopping devices	X		\Box	6.3	Fire Service Operation (84-88 ed)	Ħ		N N N
1.6	Final and emergency terminal stopping devices	X			6.4	Fire Service Operation (89-00 ed)		X	
3.7	Car leveling and anticreep devices	X							
	The state of the s								



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwaiter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

Sheldon Hall Oswego University Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI # S-111

CNYEI W.O. # 080604-00-04D1-I

1.7. ELEVATOR MAINTENANCE REPORT – ELEVATOR #1 SHELDON HALL:

Oswego College provided CNY with a copy of the last 6-months of elevator maintenance records for this elevator. Based on those reports it appears that concerns with consistent shutdowns is likely a result of failing relays and increases our concern that the controller microprocessor could fail catastrophically. Although the reports show that the elevator maintenance contractor has been attentive to the problems, it is likely that an increased frequency of shutdowns can be expected.



2. ELEVATOR #2 LANIGAN HALL

2.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:

- 2.1.1. <u>CONTROLLER</u>: The existing Dover ice-cube relay based elevator controller was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1966 by the Dover Elevator Company which was purchased by Thyssen-Krupp Elevator Company in 1999. The existing relay controller is significantly past its expected 20-year life span.
 - 2.3.1.1. A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies. The Dover controller has exceeded the 20-year life span by more than double. Replacement of the existing controller will provide increased reliability, improve functionality, and enhanced safety through fire service capability.
 - 2.1.2. <u>HOISTING COMPONENTS</u>: The existing 20-HP belt drive motor, valve and hydraulic reservoir should be replaced at the time of the controller upgrade. The existing cylinder is a single-bottom cylinder and should be replaced as soon as possible. It is not required to do the controller replacement at the time of the cylinder replacement but it is recommended. The existing cylinder should have a QEI certified witnessing of the cylinder pressure test as soon as possible to verify its current integrity.
 - 2.1.3. DOORS: Front operation.
 - 2.1.3.1. The existing light ray and safety edge (boot) type door detection should be replaced with infrared type door detectors as part of the controller upgrade.
 - 2.1.3.2. The existing Dover model door operator is in poor condition and should be replaced as part of the next elevator controller upgrade.
 - 2.1.3.3. New door restrictors are required to be provided at the time of the door operator replacement.
 - 2.1.3.4. The hoistway doors should be tested for ACBM. If the doors contain ACBM, they should be replaced, if not, they can likely be retained.
 - 2.1.3.5. The existing hoistway door tracks will be required to be replaced if the hoistway doors are replaced. If the doors are retained the existing



- tracks may be retained. The existing door gibs and rollers should be replaced at the time of the controller.
- 2.1.3.6. The existing interlocks and limit switches should be replaced at the time of controller upgrade.
- 2.1.3.7. The existing car doors are in fair condition and likely can be maintained.
- 2.1.4. <u>CALL STATIONS</u>: The existing hall call stations in the lobbies do not conform to current ADA standards and will require replacement at the time of the controller replacement.
 - 2.1.4.1. The car operating panel will require replacement at the time of the controller replacement to comply with current elevator codes for fire service.

2.1.5. CAB:

- 2.1.5.). The cab was found to be in good condition and can likely be retained.
- 2.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The lamps should be provided with a protective cover to prevent breakage.
- 2.1.5.3. It is recommended that the height of handrails be verified to be installed between 34" and 38" to the top to conform to ADA requirements.

2.1.6. ADDITIONAL COMPONENT SUMMARY:

- 2.1.6.1. The elevator pit is required to have a pit ladder installed.
- 2.1.6.2. The existing traveling cables should be replaced sooner than later. The cloth covered cables are subject to failure and should be replaced sooner than later.
- 2.1.6.3. The existing pit switch is worn and should be replaced at the time of modernization.



2.2 PHOTOS:



Main Lobby Floor Landing



Existing Machineroom



Oswego College Elevator Upgrade Study #003291G



Machineroom and Existing Disconnecting Means.



Existing Pit and Piston.



Oswego College Elevator Upgrade Study #003291G



Top of Car and Exist Door Operator.



Exist Car Operating Panel and Fire Service Add-On Panel.



2.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:

2.3.1. ELECTRICAL:

- 2.3.1.1. The existing disconnecting means appears to be in good condition and can be retained. It is recommended that the main line ground be verified prior to replacement of the controller. If fire sprinklers are added to the machineroom or the hoistway, a new shunt-trip type disconnect would be required.
- 2.3.1.2. The existing cab lighting and fan disconnect could not be tested because their location was not readily apparent. In the event of a modernization a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible the cab lighting and fan should be connected to an emergency generator.
- 2.3.1.3. The existing machineroom lighting is required to be protected against breakage. A new machineroom GFCI protected convenience outlet is required at the time of the controller upgrade.
- 2.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of the controller upgrade.

2.3.2. FIRE ALARM:

- 2.3.2.1. Annual testing of the integrated Fire Alarm/Ventilation/and Elevator recall circuits is recommended.
- 2.3.2.2. At the time of the controller upgrade it will be necessary to provide the fireman's flashing hat signal to the elevator car from any FAID located in the machineroom or hoistway.
- 2.3.2.3. The existing smoke detector in the hoistway is not permitted unless a new shaft vent is installed which is operated by a smoke detector or if the shaft is provided with fire sprinklers.

2.3.3. HVAC:

- 2.3.3.1. The existing machineroom may require additional ventilation. A review of the current heating and cooling is recommended.
- 2.3.3.2. There is no vent in the hoistway. A vent is not currently required in an elevator shaft that penetrates 3 stories or less, therefore it is not likely that a vent will be required for this shaft unless the occupancy changes.



2.3.4. COMMUNICATIONS:

2.3.4.1. A new hands-free telephone will be required in the car at the time of the controller replacement.

2.3.5. PLUMBING:

2.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required to be added in an existing elevator pit as part of a modernization.

2.3.6. GENERAL CONSTRUCTION:

- 2.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.
- 2.3.6.2. The top of the shaft appears to contain a mudded type of fire proofing. It is recommended that it be tested for ACBM.

2.3.7. FIRE PROTECTION:

2.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway, they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added, a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.



2.4. OPINION OF PROBABLE COST ELEVATOR #2 LANIGAN HALL:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2009.

Hydraulic Cylinder Replacement Only: \$35,000-\$40,000 Elevator Controller, Power Unit: \$70,000-\$75,000

New Hoistway and Elevator Car doors and Infrared detectors, Door Operator, \$20,000-\$25,000

Total for elevator work: \$150,000

2.5. EQUIPMENT INVENTORY ELEVATOR #2 LANIGAN HALL:

Year of Construction: 1966

Manufacturer: Dover (Thyssen-Krupp)

Type: Passenger Capacity: 2000 Lbs.

100 FPM (Measured speed NL: 111 FPM/up 92 FPM/dn)

Serial # E-24554

3 stop: 1, 2, 3 (3rd floor is security access only)

Fire Service: Fire Service Overlay

Recall Level: 1

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

Piston Diameter: 5-7/16"

HP: 20 Belt Drive

NL= 200/ WP= 307/ RP= 320

240V Y-Delta start Emergency Power: None Last Test 7/07, QEI: No

Doors:

Center Opening: 42" Operator: Dover

Protection: Light-ray/ Safety edge

ADA: No

Fixtures: Mechanical push button (FS panel added)

Phone: No

Cab Dimensions: 6'-8"W x 4'-2"D x 8'-0"H (Drop ceiling at 7'-5")


Finish: Steel w/ SS trim Handrails: 2" SS @ 39"



2.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyel.com

Lanigan Hall #2 Oswego University Oswego, NY 00000

Owner: Oswego State University of New York					
Туре	Passenger				
Rated Load	2000				
Year Constructed	1966				
Manufacturer	Dover				

Date of Inspection	6/3/2008
Inspector	Chris Duke
QEI Certification #	S-111
QEI Cert. Issuer	NAESA International
Workorder Designator	080604-00-04D2-I
Authoritative Jurisdiction	State University of New York

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason
Car lighting and receptacles	Item 1.5	Emergency light could not be checked (power source location unknown)
Car lighting and receptacles	Item 1.5	Fixture cover laying on drop ceiling panel
Relief valves	Item 2.31	QEI witnessing of tests required
Car top light and outlet	Item 3.2	Car Top Light shall be protected
Traveling cables and junction boxes	Item 3.16	Junction box covers missing
Pit access lighting, stop switch and condition	Item 5.1	Pit Ladder Required



Lanigan Hall #2	Page	2
Oswego University	Date of Inspection	6/3/2008
Oswego, NY 00000	Inspector	Chris Duke
Owner: Oswego State University of New York	Workorder Designator	080604-00-04D2-I

	Checklist for Hydra			ato	r - Pe	riodic Inspection Report			
Interio	r of Car	OK	NG	NA	3.9	Floor and emergency identification numbering	OK	NG	NA
1.1	Door reopening device	X			3.10	Hoistway construction	XXXXXX	H	H
1.2	Stop switches	띩	H	H	3.11	Hoistway smoke control	X	H	
1.3	Operating control devices	NNN	Ħ	Ħ	3.12	Pipes wiring, and ducts	X	H	H
1.4	Sills and car floor	X	H	H	3.13	Windows, projections, recesses, and setbacks	X		H
1.5	Car lighting and receptacles	H	X	Ħ	3.14	Hoistway clearances	X	H	H
1.6	Car Emergency signal	X	X	H	3.15	Multiple hoistways	H	一	X
1.7	Car door/gate	X	Ħ	П	3.16	Traveling cables and junction boxes	H	X	
1.8	Door closing force	X	Ħ	Ħ	3.17	Door and gate equipment	X	P	Ħ
1.9	Power closing of doors/gates	Ä	Ħ	X	3.18	Car frame and stiles	XXX	H	H
1.10	Power opening of doors/gates	Ħ	Ħ	X	3.19	Guide rails fastening and equipment	X	H	Ħ
1.11	Car vision panels and glass car doors	H	H	X	3.20	Governor rope	H	H	X
1.12	Car enclosure	X	Ħ		3.21	Governor releasing carrier	Ħ	Ħ	X
1.13	Emergency exit	X	Ħ	Ħ	3.22	Wire rope fastening and hitch plate	H	Ħ	X
1.14	Ventilation	X	Ħ	П	3.23	Suspension rope	Ħ	Ħ	X
1.15	Signs and operating device symbols	X	Ī	Ħ	3.30	Speed test	П	Ħ	X
1.16	Rated load, platform area and data plate	X	Ħ	Ħ	3.31	Slack rope device roped-hydraulic elv 1989	Ħ	H	X
1.17	Standby power operation	X	Ħ	Ħ		and later	_		2000
1.18	Restricted opening of car/hoistway doors	XXXXXXX		X	3.32	Traveling Sheave roped-hydraulic elv 1989 and later			X
1.19	Car ride	X			3.33	Counterweight			X
Machin	e Room	_				e Hoistway		-	
2.1	Access to machine space	×			4.1	Car platform guard	X		
2.2	Headroom	X			4.2	Hoistway doors	X	F	Ħ
2.3	Lighting and receptacles	X			4.3	Vision Panels	Ħ	一	X
2.4	Machine space	X			4.4	Hoistway door locking devices	×	Ħ	Ħ
2.5	Housekeeping	X			4.5	Access to Hoistway	X	П	Ħ
2.6	Ventilation	XXXXXXXX			4.6	Power closing of hoistway doors	XX XXXXX	H	n
2.7	Fire Extinguisher	×			4.7	Sequence operation	m	П	X
2.8	Pipes,wiring, and ducts	×			4.8	Hoistway enclosure	X	\Box	ī
2.9	Guarding of exposed auxilary equipment	×			4.9	Elevator Parking devices	F	Fi	X
2.10	Numbering of elevators, machines and disconnect switches	X			4.10	Emergency doors blind hoistway			
2.11	Disconnecting means and control	X			4.12	Standby power selection switch	Ц		X
2.12	Controller wiring, fuses grounding, etc.	X X			Pit	Mar Transport and the second s	-		Local
2.13	Govenor, overspeed switch and seal			X	5.1	Pit access lighting, stop switch and Condition		×	H
2.14	Code data plate	X			5.2	Bottom clearance, runby and minimum refuge space	X		
2.30	Hydraulic Power Unit	X			5.3	Final and emergency terminal stopping	X		
2.31	Relief valves				5.5	devices	124		
2.32	Control valve	X			5.4	Normal terminal stopping devices	X		
2.33	Tanks	X			5.5	Traveling cables	X		
2.34	Flexible hydraulic hose and fitting assemblies				5.6	Governor-rope tension devices	X		
2.35	Supply Line and Shutoff Valve	X			5.7	Car Frame and platform	X		
2.36	Hydraulic Cylinders	X			5.8	Car safeties and guiding members	X		
2.37	Pressure Switch			X	5.11	Plunger and cylinder	X		
2.38	Roped water hydraulic elevators			X	5.12	Car buffer	X		
Top of	Car				5.13	Guiding members	XXXXXXX		
3.1	Top-of-car stop switch	X			5.14	Supply piping	X		
3.2	Car top light and outlet	X XXXX	× □		Firefig	hter's Service		_	
3.3	Top-of-car operating device	×			6.1	Fire Service Operation (73-80 ed)			X
3.4	Top-of-car clearance and refuge space	X			6.2	Fire Service Operation (81-83 ed)			×
3.5	Normal terminal stopping devices	×			6.3	Fire Service Operation (84-88 ed)			X
3.6	Final and emergency terminal stopping devices				6.4	Fire Service Operation (89-00 ed)			X
3.7	Car leveling and anticreep devices	×							
3.8	Top emergency exit	X							



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwalter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

Lanigan Hall #2 Oswego University Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI# S-111

CNYEI W.O. # 080604-00-04D2-1

2.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #2 LANIGAN HALL:

Oswego College provided CNY with a copy of the last 6-months of elevator maintenance records for this elevator. Based on those reports it appears that concerns with consistent shutdowns are likely a result of failing ice-cube relays due to age. Ice-cube relays are widely available for replacement, however it's likely that the relays will continue to fail as the age of the equipment increases. An increase in the frequency of shutdowns can be expected.



3. ELEVATOR #3 PENFIELD LIBRARY

3.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:

- 3.1.1. <u>CONTROLLER</u>: The existing Otis Elevator relay based elevator controller was found to be in very poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1966 by Otis Elevator Company. A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies.
 - 3.1.1.1. The Otis controller has more than doubled its expected 20-year life span and should be upgraded sooner than later. The addition of a new controller will provide increased reliability, improve functionality, and enhanced safety capability with fire service.
- 3.1.2. HOISTING COMPONENTS: The existing 50-HP belt drive motor, valve and hydraulic reservoir should be replaced at the time of the controller upgrade. Maintenance records indicate that the valve has consistent problems and should be replaced sooner than later. The existing cylinder is a single-bottom and should be replaced as soon as possible. It is not required to upgrade the controller at the time of the cylinder replacement, but it is recommended. It is recommended that a QEI certified witnessing of the cylinder pressure test be performed as soon as possible to verify the integrity of the cylinder.
- 3.1.3. DOORS: Front operation.
 - 3.1.3.1. The existing infrared door detector can likely be maintained.
 - 3.1.3.2. The existing Otis model door operator is in poor condition and should be replaced as part of the elevator controller upgrade.
 - 3.1.3.3. New door restrictors are required to be provided at the time of the door operator replacement
 - 3.1.3.4. The existing hoistway doors should be tested for ACBM. If the ACBM is found to be present, the doors should be replaced. If the doors do not contain ACBM, they can likely be retained.
 - 3.1.3.5. The existing hoistway door tracks will require replacement if the hoistway doors are replaced. If the doors are retained, they can likely be retained. The door rollers and gibs should be replaced at the time of the controller upgrade.



- 3.1.3.6. The existing interlocks and limit switches should be replaced at the time of controller upgrade.
- 3.1.3.7. The existing car doors are in fair condition and can likely be retained.
- CALL STATIONS: The existing hall call stations in the lobbies do not conform to current ADA standards and require upgrade.
 - 3.1.4.1. The car operating panel will require replacement at the time of the controller upgrade to comply with current elevator codes for fire service.

3.1.5. CAB:

- 3.1.5.1. The cab was found to be in fair condition and likely be retained, however there appeared to be some rust on the top of the cab which should be cleaned up and repainted to protect against further wear.
- 3.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the renovation.
- 3.1.5.3. The existing handrails should be verified to assure that they are located between 34" and 38" to the top.

3.1.6. ADDITIONAL COMPONENT SUMMARY:

- 3.1.6.1. The elevator pit will be required to have a pit ladder installed at the time of the controller upgrade.
- 3.1.6.2. The existing pit switch is worn and should be replaced at the time of modernization.
- 3.1.6.3. The existing traveling cable is cloth covered and subject to failure. The cable should be replaced at the time of the controller replacement.



3.2. PHOTOS:



Main Lobby Floor Landing



Existing Machine space



126 North Salina St. Suite 305 Syracuse, NY 13202 Ph (315) 425-0428 Fax (315) 425-1232 www.cnyelevatorconsultants.com Copyright © 2008



Machine space and existing piping



Existing Valves and Pump.





Existing Bottom of Car and Piston



Existing Piston and Pit





Existing Top of Car



Existing Car Operating Panel



3.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:

3.3.1. ELECTRICAL:

- 3.3.1.1. The existing disconnecting means is knife-blade type and should be replaced sooner than later. A fused disconnect is necessary to prevent the motor from being damaged in the event of a locked rotor condition. It is necessary to verify that there is a proper ground prior to the installation of the controller upgrade. If sprinklers are added to the machineroom or the hoistway, a shunt trip type disconnecting means would be required.
- 3.3.1.2. The existing cab lighting and fan disconnect could not be tested because its location was not readily apparent. In the event of a modernization, a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible the cab lighting and fan should be connected to an emergency generator.
- 3.3.1.3. The existing machineroom lighting is required to be protected against breakage. A new machineroom GFCI protected convenience outlet is required at the time of the controller upgrade.
- 3.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of the controller upgrade.

3.3.2. FIRE ALARM:

- 3.3.2.1. The installation of new fire alarm devices for elevator recall will be required to be provided at the time of the controller upgrade.
- 3.3.2.2. The existing hoistway vent is required and should be tested to verify proper operation.

3.3.3. HVAC:

- 3.3.3.1. At the time of the controller upgrade a new machineroom will be required. It will be necessary to provide new ventilation to the room. Machineroom ventilation should include smoke and heat dampers to protect openings in the event of fire.
- 3.3.3.2. The existing hoistway vent may not be currently operable. It is recommended that the hoistway vent be tested for proper operation. A vent would be required in the shaft for this occupancy unless the building were fully sprinklered.



3.3.4. COMMUNICATIONS:

3.3.4.1. A new hands-free telephone will be required in the car at the time of the controller replacement.

3.3.5. PLUMBING:

- 3.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.
- 3.3.5.2. The existing piping in the machineroom will be required to be removed or separated if the existing machineroom location is maintained.

3.3.6. GENERAL CONSTRUCTION:

- 3.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.
- 3.3.6.2. At the time of modernization it will be required to separate the elevator equipment from the surrounding mechanical room. Separation is required to be by means of 2-hr rated assembly. Where penetrations are required for duct ventilation, they are required to be adequately protected by opening protectives. A fire rated machineroom door will be required with self-closing self-locking hardware.

3.3.7. FIRE PROTECTION:

- 3.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway, they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added to the machine spaces, a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.
- 3.3.7.2. An ABC type fire extinguisher is required to be in the machineroom.



3.4. OPINION OF PROBABLE COST ELEVATOR #3 PENFIELD:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2009.

Hydraulic Cylinder Replacement Only: \$40,000-\$45,000 Elevator Controller, Power Unit: \$80,000-\$85,000

New Hoistway and Elevator Car doors, Door Operator \$23,000-\$27,000

Total for elevator work: \$178,000

3.5. EQUIPMENT INVENTORY ELEVATOR #3 PENFIELD:

Year of Construction: 1966 Manufacturer: Otis 20 HICL

Type: Passenger Capacity: 2500 Lbs.

200 FPM (Measured speed NL: 218 FPM/up 181 FPM/dn)

Sales # 206686 Serial # 226685 BP

4 stop: B, 1, 2, 3

Fire Service None

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

Cylinder OD: 5-7/16" HP: 40 Belt Drive

460V EECO valve

Emergency Power: None Last Test 8/07, QEI: No

Doors:

Center Opening: 42" Operator: Otis

Protection: Infrared detector

ADA: No

Fixtures: Mechanical Pushbutton

Phone: No

Cab Dimensions: 6'-8"W x 4'-3"D x 8'-0"H (Drop ceiling at 7'-4")

Finish: Steel w/ SS trim

Handrails: 2" SS



3.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyel.com

Penfield Library #3 Oswego university Oswego, NY 00000

Owner: Oswego State University of New York

Туре	Passenger	
Rated Load	2500	
Year Constructed	1966	
Manufacturer	Otis	

Date of Inspection	6/3/2008
Inspector	Chris Duke
QEI Certification #	S-111
QEI Cert. Issuer	NAESA International
Workorder Designator	080604-00-04D3-I
Authoritative Jurisdiction	State University of New York

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason
Car lighting and receptacles	Item 1.5	Emergency light could not be checked (power source location unknown)
Signs and operating device symbols	Item 1.15	An approved pictorial sign shall be posted that reads: IN FIRE EMERGENCY, DO NOT USE ELEVATOR, USE EXIT STAIRS
Lighting and receptacles	Item 2.3	Machine room lighting not protected
Fire Extinguisher	Item 2.7	ABC type fire extinguisher required to be provided in a location convenient to the machine room access door
Relief valves	Item 2.31	QEI witnessing of tests required
Flexible hydraulic hose and fitting assemblies	Item 2.34	Flexible hoses require replacement date data tag
Car top light and outlet	Item 3.2	Car Top Light shall be protected
Top-of-car operating device	Item 3.3	Inspection speed is in excess of 150 ft/min - (recorded speed 218 ft/min)
Hoistway enclosure	Item 4.8	Fire-resistive construction must meet building code requirements (missing full concrete block in hoistway between B and 1st floors)
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection
Pit access lighting, stop switch and condition	Item 5.1	Pit Light Switch must be accessible from pit access door

Inspector's Signature

Penfield Library #3	Page	2		
Oswego university Oswego, NY 00000 Owner: Oswego State University of New York	Date of Inspection	6/3/2008		
	Inspector	Chris Duke		
	Workorder Designator	080604-00-04D3-I		

Owne	r: Oswego State University of New York					order Designator	080604-00-04	D3-I		
	Checklist for Hydr				or - Pe	riodic Inspection	Report			
Interi	or of Car	OK	NG	NA	3.9	Floor and emergency identif	Scation numbering	OK X	NG	NA
1.1	Door reopening device	X			3.10	Hoistway construction	icación numbering	X	H	H
1.2	Stop switches	X	Ħ	Ħ	3.11	Hoistway smoke control			H	H
1.3	Operating control devices		Ħ	Ħ	3.12	Pipes wiring, and ducts		X	Ħ	H
1.4	Sills and car floor	X	ñ	F	3.13	Windows, projections, reces	ses, and setbacks	X	Ħ	H
1.5	Car lighting and receptacles	\Box	X	Ħ	3.14	Holstway clearances		X	H	H
1.6	Car Emergency signal	X			3.15	Multiple hoistways		П	Ħ	X
1.7	Car door/gate	X			3.16	Traveling cables and junctio	n boxes	X		
1.8	Door closing force	X			3.17	Door and gate equipment		X		
1.9	Power closing of doors/gates			X	3.18	Car frame and stiles		X X X		
1.10	Power opening of doors/gates			X	3.19	Guide rails fastening and eq	uipment	X		
1.11	Car vision panels and glass car doors			X	3.20	Governor rope				X
1.12	Car enclosure	X	\Box		3.21	Governor releasing carrier				X
1.13	Emergency exit	X			3.22	Wire rope fastening and hite	ch plate			X
1.14	Ventilation	X		Ш	3.23	Suspension rope				X
1.15	Signs and operating device symbols		X		3.30	Speed test				X
1.16	Rated load, platform area and data plate	×			3.31	Slack rope device roped-hyd	fraulic elv 1989			X
1.17	Standby power operation	X	\sqcup		2 22	and later	lesselle als 1000			[V]
1.18	Restricted opening of car/hoistway doors			X	3.32	Traveling Sheave roped-hyd and later	raulic elv 1989	Ш		X
1.19	Car ride	X	\Box		3.33	Counterweight				X
	ne Room		_	_	Outsid	e Hoistway		-	-	
2.1	Access to machine space	X	\vdash	닏	4.1	Car platform guard		X		
2.2	Headroom	M			4.2	Hoistway doors		X		
2.3	Lighting and receptacles	님	M		4.3	Vision Panels				X
2.4	Machine space	Ä	\vdash	님	4.4	Hoistway door locking device	es	X		
2.5	Housekeeping	M	님	님	4.5	Access to Hoistway		X		
2.6	Ventilation			님	4.6	Power closing of hoistway de	oors	XXXX		
2.7	Fire Extinguisher	님	M	닐	4.7	Sequence operation		X		
2.8	Pipes,wiring, and ducts	X	\vdash	님	4.8	Hoistway enclosure			X	
2.9	Guarding of exposed auxiliary equipment	A	님		4.9	Elevator Parking devices				X
2.10	Numbering of elevators, machines and disconnect switches	X			4.10	Emergency doors blind hoist	tway			
2.11	Disconnecting means and control	X			4.12	Standby power selection sw	itch			X
2.12	Controller wiring, fuses grounding, etc.	XXXXX	ö	H	Pit			Contra	1.55	LOS ICA
2.13	Govenor, overspeed switch and seal	X	\Box	Ħ	5.1	Pit access lighting, stop swit	ch and condition		X	
2.14	Code data plate	X	\Box	\Box	5.2	Bottom clearance, runby an	d minimum refuge	X		
2.30	Hydraulic Power Unit	X				space	al abanatas			
2.31	Relief valves				5.3	Final and emergency termin devices	al stopping	X	<u></u> _	
2.32	Control valve				5.4	Normal terminal stopping de	evices	X		
2.33	Tanks	X			5.5	Traveling cables		X	Ħ	Ħ
2.34	Flexible hydraulic hose and fitting assemblies		X		5.6	Governor-rope tension device	es	Ī	Ħ	Ħ
2.35	Supply Line and Shutoff Valve	X			5.7	Car Frame and platform		X	П	ī
2.36	Hydraulic Cylinders	X			5.8	Car safeties and guiding me	mbers	X	Ħ	Ħ
2.37	Pressure Switch			X	5.11	Plunger and cylinder		X	\Box	ī
2.38	Roped water hydraulic elevators			X	5.12	Car buffer		×		Ħ
Тор о	f Car				5.13	Gulding members		XXXXXXXXX		
3.1	Top-of-car stop switch	X			5.14	Supply piping		X		
3.2	Car top light and outlet				Firefig	hter's Service		-	0.00	-
3.3	Top-of-car operating device		X		6.1	Fire Service Operation (73-8	30 ed)			X
3.4	Top-of-car clearance and refuge space	X			6.2	Fire Service Operation (81-8	33 ed)			X
m, 1 m.	Normal terminal stopping devices	X			6.3	Fire Service Operation (84-8	38 ed)			X
3.5	The state of the s	X			6.4	Fire Service Operation (89-0	00 ed)			X
3,6	Final and emergency terminal stopping devices		_	_			4	_		_
		X		B		,		_		



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwaiter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

Penfield Library #3 Oswego university Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI # S-111

CNYEI W.O. # 080604-00-04D3-I

3.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #3 PENFIELD LIBRARY:

Oswego College provided CNY with a copy of the last 6-months of elevator maintenance records for this elevator. Based on those reports it appears that concerns with consistent shutdowns are likely a result of the hydraulic valve. The 40-year old valve has outlived its expected lifespan and should be replaced as part of an overall upgrade to the controller. As the valve continues to age it will become increasingly difficult to maintain the equipment and an increase in shutdowns can likely be expected.



4. ELEVATOR #4 COOPER DINING HALL

4.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:

- 4.1.1. <u>CONTROLLER</u>: The existing Dover Elevator relay based elevator controller was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1964 by the Dover Elevator Company which was sold to Thyssen-Krupp Elevator Company in 1999. The existing controller has exceeded its expected life span of 20-years and should be replaced sooner than later.
 - 4.1.1.1 A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies. The Dover controller exceeded the expectancy by more than double. Upgrading of the controller will provide increased reliability, improved functionality, and enhanced safety with fire service.
- 4.1.2. <u>HOISTING COMPONENTS</u>: The existing 10 HP belt drive motor, valve, and hydraulic reservoir should be replaced at the time of the controller upgrade. The existing cylinder is a single bottom and should be replaced as soon as possible. It is not required to replace the controller at the time of the cylinder replacement, but it is recommended. A QEI certified witnessing of the cylinder pressure test is required as soon as possible to verify the integrity of the cylinder.
 - 4.1.2.1. It is likely that a moderate increase in speed for this elevator could be included as part of the hoisting component upgrade.
- 4.1.3. DOORS: Front Door operation.
 - 4.1.3.1. There is currently no light ray or other electronic detection which is not permitted under the current ADA standards. The existing safety edge (boot) type door detection was found to be damaged as well. The door detection should be upgraded with infrared type door detectors sooner than later.
 - 4.1.3.2. The existing Dover door operator is in poor condition and should be replaced as part of the elevator controller upgrade.
 - 4.1.3.3. New door restrictors are required to be provided at the time of the door operator replacement.



- 4.1.3.4. The existing hoistway doors should be tested for ACBM. If the doors are found to contain ACBM, they should be discarded. If the doors do not contain ACBM, they may be retained.
- 4.1.3.5. The existing hoistway door tracks will require replacement if the hoistway doors are replaced. If the doors are retained, the tracks can likely be retained. The rollers and gibs should be replaced at the time of the controller upgrade.
- 4.1.3.6. The interlocks and limit switches should be replaced at the time of the controller upgrade.
- 4.1.3.7. The existing car doors are in fair condition and can likely be maintained.
- 4.1.4. <u>CALL STATIONS</u>: The existing hall call stations do not conform to current ADA standards and are required to be upgraded at the time of the controller upgrade.
 - 4.1.4.1. The car operating panel will require replacement at the time of the controller upgrade to comply with current elevator codes for fire service.

4.1.5. <u>CAB</u>:

- 4.1.5.1. The cab was found to be in good condition and can likely be retained.
- 4.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the repoyation.
- 4.1.5.3. The height of the existing handrails should be verified to be within 34"-38" to the top to comply with current ADA standards.

4.1.6. ADDITIONAL COMPONENT SUMMARY:

- 4.16.1. The existing pit switch is worn and should be replaced at the time of modernization.
- 4.16.2. The existing traveling cables are cloth covered and subject to failure. The cables should be replaced as part of the elevator controller replacement.



4.16.3. There was no cross head data plate. A verification of the cross head data plate information should be included in the renovation and a data plate installed.

4.2. PHOTOS:



Main Lobby Floor Landing



Existing Machineroom and Motor Starter



Machineroom, Existing Controller and Disconnect Switch





Bottom of Car and Existing Piston



Existing Pit and Cylinder





Top of Car and Exist Door Operator



Existing Car Operating Panel



4.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:

4.3.1. ELECTRICAL:

- 4.3.1.1. The existing disconnecting means is a knife blade type and should be replaced sooner than later. A fused disconnect is required to prevent damage to the motor in the event of a locked rotor condition. The disconnect also does not have a grounded connection back to the building ground which will be required at the time of the next modernization. If the machineroom is provided with fire sprinklers as part of the renovation project, a new shunt trip breaker would be required.
- 4.3.1.2. The existing cab lighting and fan disconnect could not be tested because their location was not readily apparent. At the time of the controller upgrade a disconnecting means for the cab lighting and fan is required in the machineroom. Where possible, the cab lighting and fan should be connected to an emergency generator.
- 4.3.1.3. The existing machineroom lighting is required to be protected against breakage. A new machineroom GFCI protected convenience outlet is required as part of any modernization
- 4.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required as part of any modernization.

4.3.2. FIRE ALARM:

4.3.2.1. Installation of new fire alarm devices for elevator recall will be required at the time of the controller upgrade.

4.3.3. HVAC:

- 4.3.3.1. The existing machineroom may require additional ventilation.
- 4.3.3.2. Currently there is no existing hoistway vent. The current occupancy and height of the building does not require a vent in the shaft.

4.3.4. COMMUNICATIONS:

4.3.4.1. A hands-free emergency phone will be required in the car at the time of controller upgrade.



4.3.5. PLUMBING:

4.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.

4.3.6. GENERAL CONSTRUCTION:

4.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.

4.3.7. FIRE PROTECTION:

4.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway, they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added to the machine spaces, a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.



4.4. OPINION OF PROBABLE COST ELEVATOR #4 COOPER:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2010.

Hydraulic Cylinder Replacement Only: \$30,000-\$35,000 Elevator Controller, Power Unit: \$65,000-\$70,000

New Hoistway and Elevator Car doors, Door Operator, Infrared detectors \$18,000-\$23,000

Total for elevator work: \$147,000

4.5. EQUIPMENT INVENTORY ELEVATOR #4 COOPER:

Year of Construction: 1964

Manufacturer: Dover (Thyssen-Krupp)

Type: Passenger Capacity: 2000 Lbs.

65 FPM (Measured speed NL: 72 FPM/up)

Sales # E-22896

2 stop: 1, 2

Fire Service None

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

Cylinder OD: 4-3/8" (Nominal)

HP: 40 (Belt Drive)

460V EECO valve

Emergency Power: None

Last Test: 7/07, QEI: No

Doors:

RH Side Slide 2 sp. Opening: 30"

Operator: Dover DC 62 Protection: Safety Edge

ADA: No

Fixtures: Mechanical push button

Phone: No

Cab Dimensions: 4'-8"W x 3'-0"D x 7'-6"H

Finish: SS Steel textured

Handrails: 2" SS



4.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyei.com

Cooper Dining Hall #4 Oswego University Oswego, ny 00000	
Owner: Oswego State Ur	niversity of New York
Туре	Passenger
Rated Load	2000
Rated Load Year Constructed	2000 1964

Date of Inspection	6/3/2008
Inspector	Chris Duke
QEI Certification #	S-111
QEI Cert. Issuer	NAESA International
Workorder Designator	080604-00-04D4-I
Authoritative Jurisdiction	State University of New York

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason			
Door reopening device	Item 1.1	Broken safety edge boot			
Car lighting and receptacles	Item 1.5	Emergency lighting could not be checked (power source location unknown)			
Emergency exit	Item 1.13	Exit Cover shall be openable without the use of special tools (currently unsecured)			
Rated load, platform area and data plate	Item 1.16	Capacity plate required in car			
Relief valves	Item 2.31	QEI witnessing of annual tests required			
Control valve	Item 2.32	Valve control shall be sealed & tagged			
Tanks	Item 2.33	Excessive oil in drip pan or on floor			
Flexible hydraulic hose and fitting assemblies	Item 2.34	Flexible hoses require replacement date data tag			
Car top light and outlet	Item 3.2	Car Top Light shall be protected			
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection			
Pit access lighting, stop switch and condition	Item 5.1	Pit Light Switch must be accessible from pit access door			

Cooper Dining Hall #4	Page	2		
Oswego University Oswego, ny 00000 Owner: Oswego State University of New York	Date of Inspection	6/3/2008		
	Inspector	Chris Duke		
	Workorder Designator	080604-00-04D4-I		

Checklist for Hydraulic Elevator - Periodic Inspection Report									
Interio	OK NG NA OK NG NA OK NG NA Interior of Car 3.9 Floor and emergency identification numbering [V]								
1.1	Door reopening device		rv.		3.9	Floor and emergency identification numbering	X		
1.2	Stop switches	X	×	H	3.10	Hoistway construction	X	님	
1.3	Operating control devices		H	Н	3.11	Hoistway smoke control	X		
1.4	Sills and car floor	싅	H	님	3.12	Pipes wiring, and ducts	X	\vdash	
1.5	Car lighting and receptacles	\boxtimes	H	H	3.13	Windows, projections, recesses, and setbacks	X		
1.6	Car Emergency signal			H	3.14	Hoistway clearances	X	님	
1.7	Car door/gate	X X	H	H	3.15	Multiple hoistways	님	님	×
1.8	Door closing force	띉	H	\exists	3.10	Traveling cables and junction boxes	X	H	H
1.9	Power closing of doors/gates	염	H	×	3.17	Door and gate equipment Car frame and stiles	음	H	
1.10	Power opening of doors/gates	H	H	X	3.19	Guide rails fastening and equipment	X	H	
1.11	Car vision panels and glass car doors	H	H	X	3.20	Governor rope	씜	H	H
1.12	Car enclosure	걸	H		3.21	Governor releasing carrier	\vdash	H	
1.13	Emergency exit	X	님	H	3.22	Wire rope fastening and hitch plate	H	H	冶
1.14	Ventilation	×	H	H	3.23	Suspension rope	H	H	쉱
1.15	Signs and operating device symbols		H	H	3.30	Speed test	H	H	Ю
1.16	Rated load, platform area and data plate	띔	걸	H	3.31	Slack rope device roped-hydraulic elv 1989	H	H	
1.17	Standby power operation	×	음		3.31	and later			
1.18	Restricted opening of car/hoistway doors				3.32	Traveling Sheave roped-hydraulic elv 1989			X
1.19	Car ride	X			3.33	and later Counterweight	П		X
Machin	e Room					e Hoistway			
2.1	Access to machine space	X			4.1	Car platform guard	X		
2.2	Headroom	X			4.2	Hoistway doors	X	Ħ	Ħ
2.3	Lighting and receptacles	X			4.3	Vision Panels		Fi	Ī
2.4	Machine space	×			4.4	Hoistway door locking devices		Ħ	
2.5	Housekeeping	×			4.5	Access to Hoistway	X X	Ħ	Ħ
2.6	Ventilation	XXXXXXXXXX			4.6	Power closing of hoistway doors	Ħ	Ħ	X
2.7	Fire Extinguisher	X			4.7	Sequence operation	X	Ħ	П
2.8	Pipes,wiring, and ducts	X			4.8	Hoistway enclosure	X	Ħ	Ħ
2.9	Guarding of exposed auxiliary equipment	X			4.9	Elevator Parking devices	X X	Ħ	X
2.10	Numbering of elevators, machines and disconnect switches	X			4.10	Emergency doors blind hoistway			
2.11	Disconnecting means and control	X			4.12	Standby power selection switch			X
2.12	Controller wiring, fuses grounding, etc.	X	Ħ		Pit				_
2.13	Govenor, overspeed switch and seal	\Box	Ī	X	5.1	Pit access lighting, stop switch and condition	Ц	X	\sqcup
2.14	Code data plate	X	\Box		5.2	Bottom clearance, runby and minimum refuge	X		
2.30	Hydraulic Power Unit	X	\Box	\Box		Space Final and emergency terminal stopping	X		
2.31	Relief valves	П	XX	Π̈́	5.3	devices			П
2.32	Control valve	\Box	X	\Box	5.4	Normal terminal stopping devices	X		
2.33	Tanks				5.5	Traveling cables	X		
2.34	Flexible hydraulic hose and fitting assemblies		\mathbb{X}		5.6	Governor-rope tension devices	X		
2.35	Supply Line and Shutoff Valve				5.7	Car Frame and platform	X		
2.36	Hydraulic Cylinders	X			5.8	Car safeties and guiding members	X		
2.37	Pressure Switch		\exists	X	5.11	Plunger and cylinder	X		
2.38	Roped water hydraulic elevators			X	5.12	Car buffer	XXXXXXX		
Top of	Car				5.13	Guiding members	X		
3.1	Top-of-car stop switch	X			5.14	Supply piping	X		
3.2	Car top light and outlet				Firefig	hter's Service			
3.3	Top-of-car operating device	X			6.1	Fire Service Operation (73-80 ed)			X
3.4	Top-of-car clearance and refuge space	X XXXX			6.2	Fire Service Operation (81-83 ed)			XXXX
3.5	Normal terminal stopping devices	X			6.3	Fire Service Operation (84-88 ed)			X
3.6	Final and emergency terminal stopping devices	X			6.4	Fire Service Operation (89-00 ed)			X
3.7	Car leveling and anticreep devices	X							
3.8	Top emergency exit	×		Ħ					
-10	A THE THE STATE OF	_	_						



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwaiter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

Cooper Dining Hall #4 Oswego University Oswego, ny 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI # S-111

CNYEI W.O. # 080604-00-04D4-1

4.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #4 COOPER:

Maintenance Reports were not available at the time this report was completed.



5A. ELEVATOR #5A HEWITT (Passenger)

5a.1 <u>EXISTING COMPONENT SUMMARY AND UPGRADE</u> <u>RECOMMENDATIONS:</u>

- 5a.1.1. <u>CONTROLLER</u>: The existing Dover ice-cube relay based elevator controller was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1966 by Dover Elevator Company which was purchased by Thyssen-Krupp Elevator Company in 1999. The controller's expected 20-year lifespan has been far exceeded and should be replaced sooner than later.
 - 5.1.1.1. A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies. The controller has more than doubled that life expectancy. The installation of a new controller will increase reliability, improve functionality, and enhance safety with fire service capability.
- 5a.1.2. <u>HOISTING COMPONENTS:</u> The existing 30-HP belt drive motor, valve, and hydraulic reservoir should be replaced at the time of the controller upgrade. The existing cylinder is a single bottom and should be replaced as soon as possible. It is not necessary to upgrade the controller at the time of cylinder replacement but it is recommended. A QEI certified witnessing of the cylinder pressure test should be performed as soon as possible to verify cylinder integrity.
- 5a.1.3. DOORS: Front Door operation.
 - 5.1.3.1. The existing infrared door detector can likely be retained.
 - 5.1.3.2. The existing Dover door operator is in poor condition and should be replaced as part of the elevator controller upgrade.
 - 5.1.3.3. New door restrictors are required to be provided at the time of the door operator replacement.
 - 5.1.3.4. Testing of the existing hoistway doors for ACBM is required. If the doors are found to be ACBM, the doors should be replaced. If the doors do not contain ACBM, they can likely be retained.
 - 5.1.3.5. The existing hoistway door tracks will require replacement if the hoistway doors are replaced. If the doors are retained the rollers and gibs should be replaced at the time of controller upgrade.



- 5.1.3.6. The interlocks and limit switches should be replaced at the time of the controller upgrade.
- 5.1.3.7. The existing car doors are in fair condition and can likely be retained.
- 5a.1.4. <u>CALL STATIONS</u>: The existing hall call stations in the lobbies do not conform to the current requirements for ADA and will be required to be upgraded at the time of the controller upgrade.
 - 5.1.4.1. The car operating panel will require replacement at the time of the controller upgrade to comply with current elevator codes for fire service.

5a.1.5. CAB:

- 5.1.5.1. The cab was found to be in fair condition and can likely be retained, however the cab top had significant rust damage and should be reviewed for necessary repairs.
- 5.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the renovation.
- 5.1.5.3. The height of the existing handrails should be verified to be between 34" and 38" to the top to comply with current ADA standards.

5a.1.6. ADDITIONAL COMPONENT SUMMARY:

- 5.1.6.1. The elevator pit is required to have a pit ladder installed.
- 5.1.6.2. The existing pit switch is worn and should be replaced at the time of the controller upgrade.
- 5.1.6.3. The existing cloth covered traveling cables are subject to failure and should be replaced sooner than later.



5a.2. PHOTOS - ELEVATOR #5A:



Main Lobby Floor Landing



Existing Machineroom





Existing machineroom, controller, and Disconnect



Bottom of Car and Existing Piston





Existing Pit and Cylinder Jack Head



Top of Car and Exist Door Operator





Existing Car Operating Panel



Smoke Vent



5a.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES - ELEVATOR #5A:

5a.3.1. ELECTRICAL:

- 5.3.1.1. The existing disconnecting means is knife-blade type and should be replaced sooner than later. A fused disconnect is necessary to prevent damage to the motor in the event of a locked rotor condition. It is recommended that a test of the ground be completed prior to installation of the upgraded controller. If the machineroom is provided sprinklers as part of the any renovation project, a new shunt trip type breaker would be required.
- 5.3.1.2. The existing cab lighting and fan disconnect could not be tested because its location was not readily apparent. In the event of a modernization, a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible the cab lighting and fan should be connected to an emergency generator.
- 5.3.1.3. A new machineroom GFCI protected convenience outlet is required at the time of the controller upgrade.
- 5.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of the controller upgrade.

5a.3.2. FIRE ALARM:

5.3.2.1. Installation of new elevator recall circuits will be required at the time of controller upgrade.

5a.3.3. HVAC:

- 5.3.3.1. The existing machineroom may require additional ventilation.
- 5.3.3.2. The existing hoistway vent may not be currently operable. It is recommended that the hoistway vent be tested for proper operation. A vent in the shaft for this building occupancy and height may not be required.

5a.3.4. COMMUNICATIONS:

5.3.4.1. A new hands-free emergency telephone is required to be provided at the time of modernization.



5a.3.5. PLUMBING:

5.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.

5a.3.6. GENERAL CONSTRUCTION:

- 5.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.
- 5.3.6.2. The top of the hoistway appears to have a mudded-type fire proofing that should be tested for ACBM.
- 5.3.6.3. The existing machineroom contains equipment not required for the elevator which will be required to be removed at the time of renovation.

5a.3.7. FIRE PROTECTION:

5.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added to the machine space, a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.



5a.4. OPINION OF PROBABLE COST ELEVATOR #5A HEWITT:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2009.

Hydraulic Cylinder Replacement Only: \$35,000-\$40,000 Elevator Controller, Power Unit: \$80,000-\$85,000

New Hoistway and Elevator Car doors, Door Operator, Infrared detectors \$25,000-\$30,000

Total for elevator work: \$175,000

5a.5. EQUIPMENT INVENTORY ELEVATOR # 5A HEWITT:

Year of Construction: 1966

Manufacturer: Dover (Thyssen-Krupp)

Type: Passenger Capacity: 2000 Lbs

150 FPM (Measured speed NL: 162 FPM/up 104 FPM/dn)

Sales # E-24555

3 stop: L, 1, 2

Fire Service None

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

HP: 30 (Belt Drive) Emergency Power: None Last Test: 7/07, QEI: No

Doors:

Center Opening: 42" Operator: Dover DC 62 Protection: Infra-red

ADA: No

Fixtures: Mechanical push button

Phone: No

Cab Dimensions: 6'-8" W x 4'-1"D x 8'-0"H (7'-4" Drop)

Finish: Steel w/SS trim

Handrails: 2" SS



5a.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyei.com

#1Hewitt Union #5A Oswego University Oswego, NY 00000

Owner: Oswego State Ur	Owner: Oswego State University of New York					
Туре	Passenger					
Rated Load	2000					
Year Constructed	1966					
Manufacturer	Dover					

Date of Inspection	6/3/2008
Inspector	Chris Duke
QEI Certification #	S-111
QEI Cert. Issuer	NAESA International
Workorder Designator	080604-00-04D5-I
Authoritative Jurisdiction	State University of New York

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason
Car lighting and receptacles	Item 1.5	Emergency lighting could not be checked (power source location unknown)
Ventilation	Item 1.14	Fan did not function
Relief valves	Item 2.31	QEI witnessing of annual tests reuired
Tanks	Item 2.33	Excessive oil in drip pan or on floor
Flexible hydraulic hose and fitting assemblies	Item 2.34	Flexible hoses require replacement date tag
Car top light and outlet	Item 3.2	Car Top Light shall be protected
Top emergency exit	Item 3.8	Emergency exit required to be hinged and locked from the outside
Pit access lighting, stop switch and condition	Item 5.1	Pit Ladder Required
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection

#1Hewitt Union #5A	Page	2	Ī
Oswego University	Date of Inspection	6/3/2008	Π
Oswego, NY 00000	Inspector	Chris Duke	Т
Owner: Oswego State University of New York	Workorder Designator	080604-00-04D5-I	

	T. Obriego Blace Officersicy of New York				WOLK	order Designator 1080604-00-04	ו-כת		
	Checklist for Hydr				or - Pe	eriodic Inspection Report			
Interi	or of Car	OK	NG	NA	3.9	Floor and emergency identification numbering	OK X	NG	NA
1.1	Door reopening device	X			3.10	Hoistway construction	X	H	H
1.2	Stop switches	X X X	$\overline{\Box}$	Ħ	3.11	Hoistway smoke control	X	Ħ	Ħ
1.3	Operating control devices	X	\Box	Ħ	3.12	Pipes wiring, and ducts	X	Ħ	
1.4	Sills and car floor	X	\Box	П	3.13	Windows, projections, recesses, and setbacks	X	Ħ	Ħ
1.5	Car lighting and receptacles		X	\Box	3.14	Hoistway clearances		П	
1.6	Car Emergency signal	X		\Box	3.15	Multiple hoistways	Ħ	Ħ	X
1.7	Car door/gate	X			3.16	Traveling cables and junction boxes	X	Ħ	Ī
1.8	Door closing force	X			3.17	Door and gate equipment	X		
1.9	Power closing of doors/gates			X	3.18	Car frame and stiles	X		
1.10	Power opening of doors/gates			X	3.19	Guide rails fastening and equipment	X		
1.11	Car vision panels and glass car doors			X	3.20	Governor rope			X
1.12	Car enclosure	X			3.21	Governor releasing carrier			X
1.13	Emergency exit	X			3.22	Wire rope fastening and hitch plate			X
1.14	Ventilation		X		3.23	Suspension rope			X
1.15	Signs and operating device symbols	X			3.30	Speed test	Ħ		X
1.16	Rated load, platform area and data plate	X			3.31	Slack rope device roped-hydraulic elv 1989			X
1.17	Standby power operation				3.32	and later			[w]
1.18	Restricted opening of car/hoistway doors	Ц		X	3.32	Traveling Sheave roped-hydraulic elv 1989 and later			X
1.19	Car ride	X			3.33	Counterweight			X
	ne Room	1777		-	Outsid	e Hoistway		_	_
2.1	Access to machine space	XXXXXXXXXX	\vdash	H	4.1	Car platform guard	X		
2.2	Headroom		H	님	4.2	Hoistway doors	×		
2.3 2.4	Lighting and receptacles	띉	님	H	4.3	Vision Panels			X
2.5	Machine space Housekeeping	띉	님	H	4.4	Hoistway door locking devices	X		
2.6	Ventilation	님	H	H	4.5	Access to Hoistway	X		
2.7	Fire Extinguisher	싎	H	H	4.6	Power closing of hoistway doors			
2.8	Pipes,wiring, and ducts	冶	H	H	4.7	Sequence operation			X
2.9	Guarding of exposed auxiliary equipment	띉	\exists	H	4.8	Hoistway enclosure	X		
2.10	Numbering of elevators, machines and	띉	H	H	4.9	Elevator Parking devices			X
2.10	disconnect switches		ш	ш	4.10	Emergency doors blind hoistway			X
2.11	Disconnecting means and control	X			4.12	Standby power selection switch			X
2.12	Controller wiring, fuses grounding, etc.				Pit	20 Si	_	_	
2.13	Govenor, overspeed switch and seal			X	5.1	Pit access lighting, stop switch and condition	Ц	×	
2.14	Code data plate	X			5.2	Bottom clearance, runby and minimum refuge space	X		
2.30	Hydraulic Power Unit	X			5.3	Final and emergency terminal stopping	X		
2.31	Relief valves	ш	X		5.0	devices			
2.32	Control valve	X			5.4	Normal terminal stopping devices	XXXXXXXXX		
2.33	Tanks		×		5.5	Traveling cables	X		
2.34	Flexible hydraulic hose and fitting assemblies		×		5.6	Governor-rope tension devices			X
2.35	Supply Line and Shutoff Valve				5.7	Car Frame and platform	X		
2.36	Hydraulic Cylinders	X			5.8	Car safeties and guiding members	X		
2.37	Pressure Switch		Ц	X	5.11	Plunger and cylinder	X		
2.38	Roped water hydraulic elevators		\Box	X	5.12	Car buffer	X		
Тор о		1777			5.13	Guiding members	×		
3.1	Top-of-car stop switch	X	님	\vdash	5.14	Supply piping	X		
3.2	Car top light and outlet		X	H	10 miles	hter's Service		-	122
3.3	Top-of-car operating device	[X]	님	H	6.1	Fire Service Operation (73-80 ed)	\vdash	H	X
3.4	Top-of-car clearance and refuge space	싎	H	H	6.2	Fire Service Operation (81-83 ed)		H	X
3.5	Normal terminal stopping devices			H	6.3	Fire Service Operation (84-88 ed)	\vdash	H	X X X
3.6	Final and emergency terminal stopping devices	_	_		6.4	Fire Service Operation (89-00 ed)	Ц		LX
3.7	Car leveling and anticreep devices	×		\vdash					
3.8	Top emergency exit		X	Ш					

This conveyance inspection was performed in compliance with the applicable provisions of ASME A17.2 Guide for Inspection of Elevators, Escalators, and Moving walks. The owner retains full responsibility to maintain this conveyance in compliance with all applicable laws, ordinances and regulations. The Authority Having Jurisdiction retains all rights and responsibilities, as defined by applicable law, regarding verification of compliance.



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwalter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

#1Hewitt Union #5A Oswego University Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI # S-111

CNYEI W.O. # 080604-00-04D5-1

5a.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #5A HEWITT UNION:

Maintenance Reports were not available at the time this report was completed.



5B. ELEVATOR #5B HEWITT (Service Car)

5b.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:

- 5b.1.1. <u>CONTROLLER</u>: The existing Dover ice-cube relay based elevator controller was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1965 by the Dover Elevator Company which was purchased by Thyssen Krupp in 1999. The expected 20-year life span for the elevator controller has been significantly exceeded and the controller should be modernized sooner than later.
 - 5.1.1.1. A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies. A new controller will provide increased reliability, improved functionality, and additional safety functions for fire service.
- 5b.1.2. HOISTING COMPONENTS: The existing 40-HP belt drive motor, valve, and hydraulic reservoir should be replaced at the time of controller upgrade. The cylinder is a single bottom and should be upgraded as soon as possible. It is not required to upgrade the controller at the time of the cylinder replacement, but it is recommended. A QEI certified witnessing of the cylinder pressure test is required as soon as possible to verify the integrity of the existing cylinder.
- 5b.1.3. The existing capacity plate in the car is incorrectly stated as 2000 lbs. At the time of construction the size of the platform was the determining factor for the minimum carrying capacity of the elevator. Based on the dimensions of the car, the capacity should be 5000 lbs. The capacity is also required to be shown on the cross head data plate which is also missing. It will be necessary to do a full-load test using 5000 lbs to verify that the existing system can meet the required minimum load carrying capacity. This test should be done as soon as possible as part of the required QEI certified witnessing of the cylinder pressure test. The corrected data plate information is required prior to planning a replacement of the current inground cylinder.
- 5b.1.4. DOORS: Front Door operation.
 - 5.1.4.1. The existing infrared door detection can likely be retained.
 - 5.1.4.2. The existing Dover door operator is in poor condition and should be upgraded at the time of the controller modernization.



- 5.1.4.3. New door restrictors are required to be provided at the time of the door operator replacement.
- 5.1.4.4. The existing hoistway doors should be tested for ACBM. In the event that the doors contain ACBM they are required to be replaced at the time of door operator replacement. If the doors do not contain ACBM, they can likely be retained.
- 5.1.4.5. The existing hoistway door tracks will be required to be replaced if the hoistway doors are replaced. Maintenance reports indicated that the doors are worn and should be replaced sooner than later.
- 5.1.4.6. The interlocks and limit switches appear to be worn and should be replaced sooner than later.
- 5.1.4.7. The existing car door can likely be retained. The existing door return panel is damaged and should be repaired.
- 5b.1.5. <u>CALL STATIONS</u>: The existing hall call stations in the lobbies do not conform to current ADA standards and require upgrades.
 - 5.1.5.1. The car operating panel will require upgrade at the time of the controller upgrade to comply with current elevator codes for fire service.

5b.1.6. CAB:

- 5.1.6.1. The cab was found to be in good condition and can likely be retained.
- 5.1.6.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the renovation.
- 5.1.6.3. The height of the handrails should be verified to be installed between 34" and 38" to the top for ADA compliance.

5b.1.7. ADDITIONAL COMPONENT SUMMARY:

- 5.1.7.1. The elevator pit is required to have a pit ladder installed.
- 5.1.7.2. The existing pit switch is worn and should be replaced at the time of the controller replacement.
- 5.1.7.3. The existing cloth covered traveling cables are subject to failure and should be replaced sooner than later.



5b.2. PHOTOS - ELEVATOR #5B:



Main Lobby Floor Landing



Existing Bottom of Car and Piston





Existing Pit and Cylinder Jack Head



Existing Door Operator



126 North Salina St. Suite 305 Syracuse, NY 13202 Ph (315) 425-0428 Fax (315) 425-1232 www.cnyelevatorconsultants.com Copyright © 2008

Oswego College Elevator Upgrade Study #003291G



Existing Top of Car



Existing Car Operating Panel



5b.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES - ELEVATOR #5B:

5b.3.1. ELECTRICAL:

- 5.3.1.1. The existing disconnecting means appears to be acceptable. A test of the ground should be completed prior to installation of the new controller. If the machineroom is provided sprinklers as part of the any renovation project, a new shunt trip breaker would be required.
- 5.3.1.2. The existing cab lighting and fan disconnect could not be tested because its location was not readily apparent. In the event of a modernization, a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible, the cab lighting and fan should be connected to an emergency generator.
- 5.3.1.3. A new machineroom GFCI protected convenience outlet is required at the time of the controller upgrade.
- 5.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of the controller upgrade.

5b.3.2. FIRE ALARM:

5.3.2.1. The installation of new Fire Alarm devices for elevator recall will be required at the time of controller upgrade.

5b.3.3. HVAC:

- 5.3.3.1. The existing machineroom may require additional ventilation.
- 5.3.3.2. The existing hoistway vent should be tested for proper operations. A vent in the shaft in this building's occupancy may not be required.

5b.3.4. COMMUNICATIONS:

5.3.4.1. A new hands-free emergency telephone will be required in the car at the time of the controller upgrade.

5b.3.5. PLUMBING:

5.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.



5b.3.6. GENERAL CONSTRUCTION:

- 5.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.
- 5.3.6.2. The top of the shaft contains a mudded-type fire proofing which should be tested for ACBM.
- 5.3.6.3. Mechanical systems not required for the elevator are not permitted in the machineroom and will require removal or separation at the time of the controller upgrade.

5b.3.7. FIRE PROTECTION:

5.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway, they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added to the machine space, a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.



5b.4 OPINION OF PROBABLE COST ELEVATOR #5B HEWITT:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2010.

Hydraulic Cylinder Replacement Only: \$50,000-\$55,000 Elevator Controller, Power Unit: \$90,000-\$95,000

New Hoistway and Elevator Car doors, Door Operator, Infrared detectors \$25,000-30,000

Total for all elevator work: \$214,000

5b.5. EQUIPMENT INVENTORY ELEVATOR #5B HEWITT:

Year of Construction: 1966

Manufacturer: Dover (Thyssen-Krupp)

Type: Passenger/Service

Capacity: 5000 Lbs (No Data or Capacity Tags)

100 FPM (Measured speed NL: 114 FPM/up 88 FPM/dn)

Sales # E-24555

3 stop: L, 1, 2

Fire Service None

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

Cylinder OD: 6-1/2" (nominal)

HP: 30 (Belt Drive)

NL: 190/ FL: 370/ RP: 460 Emergency Power: None Last Test: 7/07, QEI: No

Doors:

Center Opening: 42" Operator: Dover DC 62 Protection: Infra-red

ADA: No

Fixtures: Mechanical push button

Phone: No

Cab Dimensions: 6'-8"W x 7'-6"D x 8'-0"H (Inside Platform = 49.5 sf)

Finish: Steel w/ SS trim

Handrails: 2" SS



5b.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyel.com

#2 Hewitt Union #5B Oswego University Oswego, NY 00000 Owner: Oswego State University of New York		Date of Inspection Inspector	6/3/2008 Chris Duke		
		QEI Certification #	S-111 NAESA International		
		QEI Cert. Issuer			
Туре	Passenger	Workorder Designator	080604-00-04D6-I		
Rated Load	4000	Authoritative Jurisdiction	State University of New York		
Year Constructed	1966				
Manufacturer	Dover				

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason
Operating control devices	Item 1.3	Broken button, switch or lens (fan switch)
Car lighting and receptacles	Item 1.5	Emergency lighting could not be checked (power source location unknown)
Signs and operating device symbols	Item 1.15	Missing Phase 1, Phase 2 Signs
Rated load, platform area and data plate	Item 1.16	Capacity plate required in car (incorrect capacity designation)
Relief valves	Item 2.31	QEI witnessing of annual tests required
Car top light and outlet	Item 3.2	Car Top Light shall be protected
Pipes wiring, and ducts	Item 3.12	Only pipes wiring and ducts used in connection with the elevator may be installed in the hoistway (Wires hanging in hoistway)
Pit access lighting, stop switch and condition	Item 5.1	Pit Ladder Required
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection



Inspector's Signature

#2 H	ewitt Union #5B				Page		2			
Oswe	go University				Date	of Inspection	6/3/2008	6/3/2008		
	go, NY 00000					ector	Chris Duke			
Owne	er: Oswego State University of New York				Worl	corder Designator	080604-00-04	D6-I		
	Checklist for Hyd	Irauli	c Ele	vate	or - P	eriodic Inspectio	n Report			
		OK	NG	NA		•		OK	NG	NA
and place of	or of Car			_	3.9	Floor and emergency ide	ntification numbering	X		
1.1	Door reopening device	X	\Box		3.10	Hoistway construction		X		
1.2	Stop switches	X			3.11	Hoistway smoke control		X		
1.3	Operating control devices				3.12	Pipes wiring, and ducts			X	
1.4	Sills and car floor	X			3.13	Windows, projections, re	cesses, and setbacks	X		
1.5	Car lighting and receptacles		X		3.14	Hoistway clearances		X		
1.6	Car Emergency signal	X			3.15	Multiple hoistways				X
1.7	Car door/gate	X			3.16	Traveling cables and june	ction boxes	X		
1.8	Door closing force	X			3.17	Door and gate equipmen	t	X		
1.9	Power closing of doors/gates			X	3.18	Car frame and stiles		XXXX		
1.10	Power opening of doors/gates			X	3.19	Guide rails fastening and	equipment	X		
1.11	Car vision panels and glass car doors			X	3.20	Governor rope				X
1.12	Car enclosure				3.21	Governor releasing carrie	er			X
1.13	Emergency exit	X			3.22	Wire rope fastening and	hitch plate			X
1.14	Ventilation	X			3.23	Suspension rope		同	Ħ	X
1.15	Signs and operating device symbols		×		3.30	Speed test		П	П	X
1.16	Rated load, platform area and data plate				3.31	Slack rope device roped-	hydraulic elv 1989			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
1.17	Standby power operation	×				and later	MUNICOSTA DOS ESTES			
1.18	Restricted opening of car/hoistway doors		П	[X]	3.32	Traveling Sheave roped-	hydraulic elv 1989			X

and later X 1.19 Car ride 3.33 Counterweight X Machine Room **Outside Hoistway** 2.1 Access to machine space Х 4.1 Car platform guard X 2.2 Headroom X 4.2 Hoistway doors 2.3 Lighting and receptacles X 4.3 Vision Panels 2.4 Machine space X 4.4 Hoistway door locking devices 2.5 Housekeeping 4.5 Access to Hoistway 2.6 Ventilation X 4.6 Power closing of hoistway doors 2.7 Fire Extinguisher 4.7 Sequence operation X 2.8 Pipes, wiring, and ducts 4.8 Hoistway enclosure 2.9 Guarding of exposed auxiliary equipment X 4.9 Elevator Parking devices X 2.10 Numbering of elevators, machines and X 4.10 Emergency doors blind hoistway disconnect switches 4.12 Standby power selection switch XXIXXIXX 2.11 Disconnecting means and control Pit 2.12 Controller wiring, fuses grounding, etc. 5.1 Pit access lighting, stop switch and condition Х 2.13 Govenor, overspeed switch and seal Х X 5.2 Bottom clearance, runby and minimum refuge 2.14 Code data plate space 2.30 Hydraulic Power Unit X 5.3 Final and emergency terminal stopping П X 2.31 Relief valves devices 2.32 Control valve 5.4 Normal terminal stopping devices X 2.33 Tanks 5.5 Traveling cables X X 2.34 Flexible hydraulic hose and fitting assemblies 5.6 X Governor-rope tension devices 2.35 Supply Line and Shutoff Valve Х X 57 Car Frame and platform X 2.36 X Hydraulic Cylinders X 5.8 Car safeties and guiding members 2.37 Pressure Switch 5.11 X Plunger and cylinder 2.38 Roped water hydraulic elevators X X 5.12 Car buffer Top of Car 5.13 Guiding members X X 3.1 Top-of-car stop switch 5.14 Supply piping X 3.2 Car top light and outlet Firefighter's Service 3.3 Top-of-car operating device 6.1 Fire Service Operation (73-80 ed) 3.4 Top-of-car clearance and refuge space 6.2 X Fire Service Operation (81-83 ed) 3.5 X Normal terminal stopping devices 6.3 Fire Service Operation (84-88 ed) X 3.6 Final and emergency terminal stopping X 6.4 Fire Service Operation (89-00 ed) devices 3.7 Car leveling and anticreep devices X 3.8 Top emergency exit

This conveyance inspection was performed in compliance with the applicable provisions of ASME A17.2 Guide for Inspection of Elevators, Escalators, and Moving walks. The owner retains full responsibility to maintain this conveyance in compliance with all applicable laws, ordinances and regulations. The Authority Having Jurisdiction retains all rights and responsibilities, as defined by applicable law, regarding verification of compliance.



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwaiter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

#2 Hewitt Union #5B Oswego University Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code and the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QEI# 5-111

CNYELW.O. # 080604-00-04D6-L

5b.7. ELEVATOR MAINTENANCE REPORT - ELEVATOR #5B HEWITT UNION:

Oswego College provided CNY with a copy of the last 6-months of elevator maintenance records for this elevator. Based on those reports it appears that concerns with consistent shutdowns are likely a result of the door operator and hoistway doors. The door operator is past its expected lifespan and should be replaced sooner than later. The hoistway doors are worn, which is not uncommon for a service elevator that is often exposed to impact while moving freight on and off the car. It is suggested that the elevator contractor review the existing gibs, rollers, and hangers to see if they should be replaced. Additionally the doors should be tested for ACBM and if they test positive they should be replaced at the time of controller upgrade.



6. ELEVATOR #6 TYLER ARTS

6.1. EXISTING COMPONENT SUMMARY AND UPGRADE RECOMMENDATIONS:

- 6.1.1. <u>CONTROLLER</u>: The existing Dover ice-cube type relay based elevator controller was found to be in poor overall condition and maintenance appeared to be adequate. This controller was installed new in 1966 by the Dover Elevator Company which was purchased by Thyssen-Krupp Elevator Company in 1999. The controller has far exceeded its expected life span of about 20 years.
 - 6.1.1.1. A 20-year life span for a controller is typical both in terms of the expected life span of the specific components but also as it relates to providing optimum efficiency with new technologies. The Dover controller has more than doubled that expectancy and should be upgraded sooner than later. A new controller will provide increased reliability, improved functionality, and enhanced safety capability with fire service.
- 6.1.2. <u>HOISTING COMPONENTS:</u> The existing 40-HP belt drive motor, valve, and hydraulic reservoir should be replaced at the time of the controller upgrade. The existing cylinder is a single bottom type and should be replaced as soon as possible. It is not required to upgrade the controller at the time of the cylinder replacement, but it is recommended. A QEI certified independent witnessing of the cylinder pressure test to verify cylinder integrity is required as soon as possible.
 - 6.1.2.1. The existing capacity plate in the car is incorrectly stated as 2000 lbs. At the time of construction the size of the platform was the determining factor for the minimum carrying capacity of the elevator. Based on the dimensions of the car the capacity should be 5000 lbs. The capacity is also required to be shown on the cross head data plate which appears to be incorrectly labeled as 4,015 lbs. It will be necessary to do a full-load test using 5000 lbs to verify that the existing system can meet the required minimum load carrying capacity. This test should be done as soon as possible as part of the required QEI certified witnessing of the cylinder pressure test. The corrected data plate information is required prior to planning a replacement of the current inground cylinder
- 6.1.3. DOORS: Front Door operation.
 - 6.1.3.1. The existing infrared door detector is in fair condition and can likely be retained.



- 6.1.3.2. New door restrictors are required to be provided at the time of the door operator replacement.
- 6.1.3.3. The existing hoistway doors should be tested for ACBM. If the doors contain ACBM, they should be replaced, if not, they can likely be retained. It is recommended that the Owner consider the appearance of the existing hoistway doors prior to making a decision on retaining them.
- 6.1.3.4. The existing hoistway door tracks will require replacement if the hoistway doors are replaced. If the doors are retained, the tracks can likely be retained. Hoistway door rollers and gibs should be replaced at the time of controller upgrade.
- 6.1.3.5. The interlocks and limit switches should be replaced at the time of controller upgrade.
- 6.1.3.6. The existing car doors are in fair condition and can likely be maintained.
- 6.1.4. <u>CALL STATIONS</u>: The existing hall call stations in the lobbies do not conform to current ADA standards and will require upgrades at the time of controller upgrade.
 - 6.1.4.1. The car operating panel will require upgrade at the time of the controller upgrade to comply with current elevator codes for fire service.

6.1.5. CAB:

- 6.1.5.1. The cab was found to be in good condition and likely be retained.
- 6.1.5.2. The existing lighting should be checked to verify that the ballasts are electronic, if not, the fixtures should be replaced. The existing lamps should be provided with a protective cover to prevent breakage at the time of the renovation.
- 6.1.5.3. The handrails will require lowering to between 34"-38" to the top of the handrail at the time of the controller upgrade.

6.1.6. ADDITIONAL COMPONENT SUMMARY:

6.1.6.1. The elevator pit ladder will require an extension to a minimum of 48" above the lowest landing at the time of the controller upgrade.



- 6.1.6.2. The existing pit switch is worn and should be replaced at the time of modernization.
- 6.1.6.3. The existing cloth cover traveling cables are subject to failure and should be replaced sooner than later.
- 6.1.6.4. The top of car operating device was found to be inoperable in the down direction. The device is required to be replaced as soon as possible.

6.2. PHOTOS:



Main Lobby Floor Landing



Oswego College Elevator Upgrade Study #003291G



3rd Level Lobby Landing

Oswego College Elevator Upgrade Study #003291G



Machineroom and Mainline Disconnect



Machineroom and Machine Starter Panel.



126 North Salina St. Suite 305 Syracuse, NY 13202 Ph (315) 425-0428 Fax (315) 425-1232 www.cnyelevatorconsultants.com Copyright © 2008



Existing Bottom of Car and Piston



Exist Pit and Pit Ladder



126 North Salina St. Suite 305 Syracuse, NY 13202 Ph (315) 425-0428 Fax (315) 425-1232 www.cnyelevatorconsultants.com Copyright © 2008

Oswego College Elevator Upgrade Study #003291G



Pit and Cylinder Jack Head



Existing Top of Car



Oswego College Elevator Upgrade Study #003291G



Existing Door Operator



Car Operating Panel



6.3. SUMMARY OF ANCILLARY SYSTEM UPGRADES:

6.3.1. ELECTRICAL:

- 6.3.1.1. The existing disconnecting means appears to be acceptable. It is recommended that tests of the ground be conducted prior to installation of a new controller. If the machineroom is provided with fire sprinklers as part of any renovation project, a new shunt trip breaker would be required.
- 6.3.1.2. The existing cab lighting and fan disconnect could not be tested because its location was not readily apparent. In the event of a modernization, a disconnecting means for the cab lighting and fan would be required in the machineroom. Where possible, the cab lighting and fan should be connected to an emergency generator.
- 6.3.1.3. A new machineroom GFCI protected convenience outlet is required at the time of controller upgrade.
- 6.3.1.4. The existing pit light is required to be protected against breakage. A new pit GFCI protected convenience outlet is required at the time of controller upgrade.

6.3.2. FIRE ALARM:

6.3.2.1. New fire alarm devices for elevator recall will be required as part of the elevator controller upgrade.

6.3.3. HVAC:

- 6.3.3.1. The existing machineroom may require additional ventilation.
- 6.3.3.2. The existing hoistway vent may not be currently operable. It is recommended that the hoistway vent be tested for proper operation. A vent in the shaft for this building's occupancy may not be required.

6.3.4. COMMUNICATIONS:

6.3.4.1. A new hands-five emergency telephone will be required in the car at the time of the controller upgrade.



6.3.5. PLUMBING:

6.3.5.1. The existing pit appeared to be dry and did not have a sump pump or drain previously installed. A new sump pump or drain is not required in an existing elevator pit as part of a modernization.

6.3.6. GENERAL CONSTRUCTION:

6.3.6.1. General construction upgrades should include any necessary maintenance to ensure that all hoistway and machineroom fire resistance ratings remain in compliance with those fire resistance ratings required at the time of original construction. Opening protectives and fire rated assemblies should be maintained to assure proper seals.

6.3.7. FIRE PROTECTION:

6.3.7.1. The existing elevator machineroom is not provided with fire sprinklers. If fire sprinklers are added to the machineroom or hoistway, they should be standard response two hundred (200°) degree Fahrenheit sprinkler heads. They should be arranged to disconnect power from the elevator immediately upon water flow. It is recommended that if sprinklers are added to the machine space a pre-action sprinkler system be provided to maximize the ability of the elevator to complete recall prior to loss of power.



6.4. OPINION OF PROBABLE COST ELEVATOR #6 TYLER:

The following opinion of probable cost (Elevator work only) assumes construction to be completed by December 2009.

Hydraulic Cylinder Replacement Only: \$50,000-\$55,000 Elevator Controller, Power Unit: \$90,000-\$95,000

New Hoistway and Elevator Car doors, Door Operator, Infrared detectors \$25,000-30,000

Total for all elevator work: \$206,000

6.5. EQUIPMENT INVENTORY ELEVATOR #6 TYLER:

Year of Construction: 1965

Manufacturer: Dover (Thyssen-Krupp)

Type: Passenger

Capacity: 5000 Lbs (crosshead data plate indicates 4,015 lbs) 100 FPM (Measured speed NL: 114 FPM/up 80 FPM/dn)

Sales # E-244558

3 stop: L, 1, 2

Fire Service None

Hoisting Type: Direct Acting Inground Single Bottom Cylinder

Cylinder OD: 6-1/2" (nominal)

HP: 40 (Belt Drive)

208V

NL: 190/ FL: 310/ RP: 330 Emergency Power: None Last Test 7/07, QEI: No

Doors:

Center Opening: 42" Operator: Dover DC 62 Protection: Infra-red

ADA: No

Fixtures: Mechanical push button

Phone: No

Cab Dimensions: 6'-8"W x 7'-8"D x 8'-0"H (Inside Platform = 50 sf)

Finish: Steel w/SS trim Handrails: 2" SS @ 39"



6.6. APPENDIX 3: QEI INSPECTION REPORTS



Hydraulic Elevator





Suite 305 126 North Salina Street Syracuse, NY 13202

Tel (315) 425-0428 Fax (315) 425-1232 inspections@cnyei.com

Date of Inspection 6/3/2008 Tyler Hall #6 Inspector Chris Duke Oswego University QEI Certification # S-111 00000 Oswego, NY Owner: Oswego State University of New York NAESA International QEI Cert. Issuer Workorder Designator 080604-00-04D7-I Type Passenger Rated Load 4000 Authoritative Jurisdiction State University of New York Year Constructed 1966 Manufacturer Dover

Inspection Items Not In Compliance Per ASME A17.1

Inspection Item	Applicable Code Reference	Failure Reason
Operating control devices	Item 1.3	Broken button, switch or lens (fan switch)
Car lighting and receptacles	Item 1.5	Emergency lighting could not be checked (power source location unknown)
Rated load, platform area and data plate	Item 1.16	Capacity plate required in car (existing 2000 lb plate in car is incorrect)
Relief valves	Item 2.31	Relief Valve shall be sealed
Relief valves	Item 2.31	QEI witnessing of annual tests required
Tanks	Item 2.33	Excessive oil in drip pan or on floor
Flexible hydraulic hose and fitting assemblies	Item 2.34	Flexible hoses require replacement date data tag
Car top light and outlet	Item 3.2	Car Top Light shall be protected
Top-of-car operating device	Item 3.3	TOC inspection not functioning properly (down operation)
Pit access lighting, stop switch and condition	Item 5.1	Provide pit light protection



Tyler Hall #6	Page	2
Oswego University	Date of Inspection	6/3/2008
Oswego, NY 00000	Inspector	Chris Duke
Owner: Oswego State University of New York	Workorder Designator	080604-00-04D7-I

		Checklist for Hydr			vato	r - Pe	eriodic Inspection Report			
1.1 Door reopening device	Interio	or of Car	OK	NG	NA	3.0	Floor and amergency identification numbering	OK.	NG	
Standby power operation Standby power op								심	H	H
Standby power operation Standby power op				H	H				H	H
Standby power operation Standby power op				岗				띉	H	H
Standby power operation Standby power op		- Alam	X	H				띉	H	H
Standby power operation Standby power op				A	H		THE PROPERTY OF THE PROPERTY O	심	H	H
Standby power operation Standby power op			X		H			H	H	X
Standby power operation Standby power op			X	H	Ħ			X	H	H
Standby power operation Standby power op		and the state of t	X	Ħ				X	Ħ	H
Standby power operation Standby power op			H	П				X	H	Ħ
Standby power operation Standby power op	1.10		\Box	П	X	3.19		X	Ħ	П
Standby power operation Standby power op	1.11	Car vision panels and glass car doors				3.20		Ħ	Ħ	X
Standby power operation Standby power op	1.12	Car enclosure	X			3.21	Governor releasing carrier			X
Standby power operation Standby power op	1.13	Emergency exit	X			3.22	Wire rope fastening and hitch plate			X
Standby power operation Standby power op	1.14	Ventilation	X			3.23	Suspension rope			X
Standby power operation Standby power op	1.15	Signs and operating device symbols	X			3.30	Speed test			X
Access to machine space X	1.16	Rated load, platform area and data plate		X		3.31	[] [[[[[[[[[[[[[[[[[[X
Access to machine space X	1.17	Standby power operation	X				The state of the s			
Access to machine space X	1.18	Restricted opening of car/hoistway doors			X	3.32				X
Access to machine space	1.19	Car ride	X			3.33		П		X
2.1 Access to machine space X			_							
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			X	Ц				X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			X	Ц	Ц	4.2				\Box
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			×	님	Н	4.3	Vision Panels			X
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			X	\vdash	\vdash	4.4	Hoistway door locking devices	X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			M	님	님	4.5	Access to Hoistway	X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			X	H	H	4.6	Power closing of hoistway doors	X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)	0.00	17 THE TOTAL BOUNDALY OF THE	띉	H	H	4.7	Sequence operation	X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			띉	H	H	4.8	Hoistway enclosure	X		
disconnect switches 2.11 Disconnecting means and control 2.12 Controller wiring, fuses grounding, etc. 2.13 Govenor, overspeed switch and seal 2.14 Code data plate 2.20 Hydraulic Power Unit 2.31 Relief valves 2.32 Control valve 2.33 Tanks 2.34 Flexible hydraulic hose and fitting assemblies 2.35 Supply Line and Shutoff Valve 2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top-of-Car stop switch 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating devices 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping devices 3.7 Pressure Switch 3.8 Normal terminal stopping 3.9 Fire Service Operation (81-83 ed) 3.1 Source Switch 3.2 Fire Service Operation (84-88 ed) 3.3 Top-of-car clearance and refuge space 3.4 Fire Service Operation (89-00 ed) 3.5 Supply terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 Fire Service Operation (84-88 ed) 3.8 Fire Service Operation (89-00 ed)			띉	H	H	4.9	Elevator Parking devices			X
Pit Controller wiring, fuses grounding, etc. X	2.10			ш		4.10	Emergency doors blind hoistway			X
2.31 Relief valves	2.11	Disconnecting means and control	X			4.12	Standby power selection switch			X
2.31 Relief valves	2.12	Controller wiring, fuses grounding, etc.	X						7	
2.31 Relief valves	2.13	Govenor, overspeed switch and seal	X					\Box	×	\vdash
2.31 Relief valves	2.14	Code data plate	×			5.2		X		
X	2.30	Hydraulic Power Unit	X			5.3		X		П
X	2.31	Relief valves		X			등의 맛말면 맛있다면 맛이 많아서 느와 자연 2000 Hebrit Substitution () 그리스 ()			
2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top of Car 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping X 5.12 Car bauffer X 5.13 Guiding members X	2.32	Control valve	X			5.4	Normal terminal stopping devices			
2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top of Car 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping X 5.12 Car bauffer X 5.13 Guiding members X		Tanks		X		5.5	Traveling cables	X		
2.36 Hydraulic Cylinders 2.37 Pressure Switch 2.38 Roped water hydraulic elevators Top of Car 3.1 Top-of-car stop switch 3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping X 5.12 Car bauffer X 5.13 Guiding members X		[지기 ^ 4 4] 할아니다 하는 아이는 아니는 아니는 아니는 아니는 아니는 아니는 아니는 아니는 아니는 아니		X	\Box	5.6	Governor-rope tension devices			X
3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 devices 3.8 Firefighter's Service 3.9 G.1 Fire Service Operation (73-80 ed) 3.0 Firefighter's Service Operation (81-83 ed) 3.1 Service Operation (81-83 ed) 3.2 Service Operation (84-88 ed) 3.3 Firefighter's Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Final and emergency terminal stopping 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 S			X	\sqcup			Car Frame and platform	X		
3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 devices 3.8 Firefighter's Service 3.9 G.1 Fire Service Operation (73-80 ed) 3.0 Firefighter's Service Operation (81-83 ed) 3.1 Service Operation (81-83 ed) 3.2 Service Operation (84-88 ed) 3.3 Firefighter's Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Final and emergency terminal stopping 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 S			X	\sqcup						X
3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 devices 3.8 Firefighter's Service 3.9 G.1 Fire Service Operation (73-80 ed) 3.0 Firefighter's Service Operation (81-83 ed) 3.1 Service Operation (81-83 ed) 3.2 Service Operation (84-88 ed) 3.3 Firefighter's Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Final and emergency terminal stopping 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 S				님	M			X		
3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 devices 3.8 Firefighter's Service 3.9 G.1 Fire Service Operation (73-80 ed) 3.0 Firefighter's Service Operation (81-83 ed) 3.1 Service Operation (81-83 ed) 3.2 Service Operation (84-88 ed) 3.3 Firefighter's Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Final and emergency terminal stopping 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 S					X			X		
3.2 Car top light and outlet 3.3 Top-of-car operating device 3.4 Top-of-car clearance and refuge space 3.5 Normal terminal stopping devices 3.6 Final and emergency terminal stopping 3.7 devices 3.8 Firefighter's Service 3.9 G.1 Fire Service Operation (73-80 ed) 3.0 Firefighter's Service Operation (81-83 ed) 3.1 Service Operation (81-83 ed) 3.2 Service Operation (84-88 ed) 3.3 Firefighter's Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Final and emergency terminal stopping 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.1 Service Operation (81-80 ed) 3.2 Service Operation (81-80 ed) 3.3 Service Operation (81-80 ed) 3.4 Service Operation (81-80 ed) 3.5 Service Operation (81-80 ed) 3.6 Service Operation (81-80 ed) 3.7 Service Operation (81-80 ed) 3.8 Service Operation (81-80 ed) 3.9 Service Operation (81-80 ed) 3.0 S							Programme and the state of the	M		\vdash
devices			씜	님	님			X		\Box
devices		[1] 사용 전 사용 등 사용 (1) 기본 사용 (1) 기본	H	띉	\vdash					[V]
devices			님	씜	님			H	H	
devices				H	H			H	H	
devices			N N	H	H			H	H	X
	5.0		(C)		, 	0.4	The Salvice Operation (05-00 ed)			
3.8 Top emergency exit	3.7		X							
	3.8	Top emergency exit	X							

This conveyance inspection was performed in compliance with the applicable provisions of ASME A17.2 Guide for Inspection of Elevators, Escalators, and Moving walks. The owner retains full responsibility to maintain this conveyance in compliance with all applicable laws, ordinances and regulations. The Authority Having Jurisdiction retains all rights and responsibilities, as defined by applicable law, regarding verification of compliance.



POSTING INSTRUCTIONS

"The most current certificate of inspection shall be on display at all times within the elevator or attached to the escalator or dumbwaiter; or the certificate shall be available for public inspection in the office of the building operator"

- Property Maintenance Code

Certificate of Inspection



THIS CERTIFIES THAT AN INDEPENDENT THIRD-PARTY QEI INSPECTION WAS PERFORMED ON:

June 3, 2008

For the following Conveyance:

Tyler Hall #6 Oswego University Oswego, NY 00000

SEE ATTACHED REPORT FOR THE RESULTS OF THIS INSPECTION

Authority Having Jurisdiction: State University of New York

This Inspection Certificate Expires in:

December 2008

This inspection certificate only indicates that a QEI certified inspector employed by CNY Elevator Inspections Inc performed a conveyance inspection complying with the requirements of the Building Code and Property Maintenance Code on the date indicated. Where non-compliant items are indicated on the attached report and as required by the Authority Having Jurisdiction and/or as required by law, regulation, or ordinance, the Owner shall correct all deficiencies as soon as possible.

QEI Inspector: Chris Duke

QE1# S-111

CNYEI W.O. # 080604-00-04D7-1

Oswego College Elevator Upgrade Study #003291G

6.7. ELEVATOR MAINTENANCE REPORT – ELEVATOR #6 TYLER:

Oswego College provided CNY with a copy of the last 6-months of elevator maintenance records for this elevator. Based on those reports it appears that concerns with consistent shutdowns are likely a result of failing icecube relays due to age. Ice-cube relays are widely available for replacement; however it's likely that the relays will continue to fail as the age of the equipment increases and an increase in the frequency of shutdowns can likely be expected.



SUPPLEMENTAL REPORT Oswego College Elevator Upgrade Study #003291G

PART S-1 Accessibility Upgrades

Under the Authority of the Department of Justice the American with Disabilities Act of 1990 (28 CFR Part 36) was issued as a design and construction guide to mandate equivalent access to required facilities for the physically impaired. Based on the ICC/ANSI A117.1-1980 edition, the guide provided strict standards for removing barriers that prevented individuals with special needs from accessing public facility and building services. Commonly referred to as "ADA" the act is effectively civil rights legislation and should not be confused with building codes.

At the time of the publication of the ADA guidelines, it was required that all public facilities provide an accessible path from a point of entry to any point where a public service is provided, referred to as the "accessible path." This could be accomplished by simply removing barriers or by providing equivalent access. Part 4.10 of the ADA guide covers specifically the use of those elevators and wheelchair lifts which are considered to be within the accessible path. Part 4.10 is directed at the removal of barriers to the elevator in relation to door operation, leveling, clear floor space, and access to controls.

Door operation can be generally described in two parts: part one provides standards for protection against making physical contact with closing doors, part two provides standards for allowing adequate time for person(s) with physical impairments to access the car before the doors close and the elevator attends to another call. Most passenger elevators are able to meet the standards for door operation. An exception that allows a "safety edge" which is a mechanical door protective device on existing elevators, has allowed many elevators to avoid upgrades to the door protection since the legislation passed 18 years ago. It should be noted however that safety edge door protection can still be a liability issue and should be replaced when feasible to prevent contact with the doors by persons who may not be physically capable of protecting themselves from injury in the event they are impacted by closing doors. It should also be noted that the current ICC/ANSI A117.1-2003 edition requires that all doors in passenger elevators open horizontally for them to be considered as part of an accessible path.

Automatic operation, and leveling within 1/2" is required for passenger elevators on an accessible path. It should be noted that not all elevators are capable of providing that standard of precise leveling and would require upgrading to be considered accessible.

Floor space requirements are intended to provide sufficient space for wheel chair access and provide proper reach to controls from inside the car. There are many options for floor space requirements on existing elevators to avoid the need for enlarging a hoistway.

Control access is broken down into three parts: visible, audible, and access. In general access is assumed to be considered "reachable" from a wheel chair but also includes the ability to locate necessary controls and information for the vision impaired. Visible elements are required to



indicate that a call has been placed, that a call has been received and that a car is traveling to those persons who can see but not hear. Audible elements are required to mimic the visual elements for persons who can hear but not see. The ICC/ANSI A117.1 2003 edition has also added the additional requirement to provide a voice annunciation of each floor and direction of travel on elevators that travel in excess of 200 feet per minute.

The most common misconception regarding ADA is that the requirements are tied to building renovation and upgrades similar to the building code requirements. In fact the requirements apply to any element that constitutes a barrier whether existing or new construction. There is no exception for elevators. While the ideal time to apply the necessary upgrades to ADA compliance may be more feasible during a controller system upgrade, the requirement to provide barrier free access on any elevator which is designated as part of accessible path became effective when the legislation passed. It is recommended that all elevators on an accessible path be upgraded to ADA compliance, however it is recognized that some elements may have barriers that are technically or financially more difficult to accomplish than others. In many cases technical infeasibility permits exceptions to such modifications, for example it is not expected that elevator hoistway is required to be enlarged to accommodate a larger elevator. On the other hand, elements like Braille tags on entrance frames and lowering of call buttons can usually be accomplished without a great deal of expense or difficulty. It should be a policy that where any single barrier element can be removed, it should be, even if it's not possible to remove all barriers at that time.

We recommend a review of the following checklist for each elevator. In some cases upgrades to full ADA compliance may be better at the time of any proposed upgrades to the elevator controllers. Where controller upgrades are not necessarily planned in the short term it is suggested that, where modest upgrades to removing barrier elements are practicable, they should be upgraded to the extent possible.

SUMMARY:

ELEVATOR #1: Sheldon

Sheldon elevator is nearly ADA compliant and could be made ADA compliant with only minor modifications.

ELEVATOR #2: Lanigan

Lanigan elevator is partly ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. Modest improvements could be made prior to renovation.

ELEVATOR #3: Penfield

Penfield elevator is partly ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. Modest improvements could be made prior to renovation.



ELEVATOR #4: Cooper

Lanigan elevator is not ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. The existing cab size cannot meet the requirements of even the exceptions for technical infeasibility. It is recommended that the existing car be reviewed to see if it can be considered as providing "equivalent facilitation" by demonstrating that the car can be shown to be adequately accessible to wheel chairs. If the car cannot be shown to be large enough to provide wheelchair access, the elevator should not be considered as a part of accessible path.

ELEVATOR #5A: Hewitt Passenger

Hewitt passenger elevator is partly ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. Modest improvements could be made prior to renovation.

ELEVATOR # 5B: Hewitt Service

Hewitt passenger elevator is partly ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. Modest improvements could be made prior to renovation.

ELEVATOR #6: Tyler

Tyler elevator is partly ADA compliant and should be upgraded to full compliance at the time of the controller upgrade. Modest improvements could be made prior to renovation.





Elevator: SHELDON ELEV #1

ADA ITEM#	DESCRIPTION	COMPLIANT? YES	NO	NOTE
	ADA STANDARDS 28CFR Part 36			,,,,,,
× 4.85.5(5)	Handrails 34" min 38" max to top		X	32"
X 4.10.1	Automatic Operation	X		
	Self Leveling within 1/2" at rated/ unrated load	×		
× 4.10.3	Hall Call Buttons	×		
	42" Center Line	×		
	3/4" min raised or flush	X		
	visual call registered	×		
	No object projects more than 4" below call station			
X 4.10.4		X		
A 4.70.4	Hall Lanterns	Х		NONE
	Passing audible 1 up / 2 dwn	X		
	72" min	×		
	Visual Element at least 2-1/2	×		
	Visible from hall call button	Х		
× 4.10.5	Holstway entrance Braille both jambs	×		NONE
	60 in. center line	X		
× 4.10.6	Door Protection	×	FINE	Safety edge exception 4.1.6(1)(k)(ii)(3)(c)(i
	20 sec delay min	0 1 1 1 1 1 1 1 1		NOT TESTED
× 4.10.7	Holstway Door Timing 5 sec. min	×		NOT TESTED
× 4.10.8	Car Door Delay 3 sec. min	×		NOT TESTED
× 4.10.9	Floor Plan (Fig. 22)	X		EXISTING
A 4.10.0	Floor plan exception 4.1.6(1)(k)(ii)(3)(c)(ii) applies? (48" x 48" min or equivalent access provided)	×		ZAIOTHO
	Door Opening 36" min	X		
× 4.10.10	Floor Surfaces comply with 4.5	×		
	1/4" max level	X		
	carpeting secured			N/A
X 4.10.11	Lighting 5fc min.	×		EMERG. NOT TESTE
× 4.10.12	Car Controls	×		
	Buttons 3/4" min. raised or flush	×		
	Braille	×		
	Visual Call Registered	×		
	Height 54" max. (side) 48" max (front)	×	BENE	
	Emergency buttons 35" min	×		
	Location front on center opening/ side on or front or side opening (fig 23 c and d)	×		
X 4.10.13	In-Car Position Indicator	X		
× 4.10.14	Emergency Communication	×		
	48 " max	Ж		
	Bell	×		
	Handset cord 29" min	X		
	Additional ICC requirements			
W 400 - 1	Additional ICC requirements		1	
× 407.3.1	Hoistway Door horizontal opening	X		
407.4.6.2.2	Buttons arranged in ascending order	×		
407.4.9.2.1	PI audible vocal over 200 fpm	×	-	N/A



Elevator: LANIGAN ELEV #2

ADA ITEM#	DESCRIPTION	COMPLIANT 7 YES	NO	NOTE
¥ 4 00 000	ADA STANDARDS 28CFR Part 36			
X 4.85.5(5)	Handralls 34" min 38" max to top		X	39"
X 4.10.1	Automatic Operation	X		
	Self Leveling within 1/2" at rated/ unrated	×		
	load	^		
× 4.10.3	Hall Call Buttons	X		
	42" Center Line		×	38"
	3/4" min raised or flush	X		
	visual call registered	×		
	No object projects more than 4" below call			
	station	×		
X 4.10.4	Hall Lanterns		X	NONE
	Passing audible 1 up / 2 dwn	-		
	72" min			
	Visual Element at least 2-1/2			
	Visible from hall call button			
X 4.10.5	Hoistway entrance Braille both jambs		X	NONE
	60 in. center line			1107.16
× 4.10.6	Door Protection	X		
	20 sec delay min	X		
× 4.10.7	Hoistway Door Timing 5 sec. min	X	1	
× 4.10.7	Car Door Delay 3 sec. min	X		
× 4.10.9			- 22	EXISTING
A 4.10.9	Floor Plan (Fig. 22)	X		EXISTING
	Floor plan exception 4.16(1)(k)(ii)(3)(c)(ii)	100		
	applies? (48" x 48" min or equivalent access	X		
	provided)	44		
	Door Opening 36" min	X		
× 4.10.10	Floor Surfaces comply with 4.5	X		
-	1/4" max level	×		
	carpeting secured			N/A
× 4.10.11	Lighting 5fc min.	X		EMERG. NOT TESTER
× 4.10.12	Car Controls		X	
	Buttons 3/4" min. raised or flush	x		
	Braille		×	
	Visual Call Registered		×	
	Height 54" max. (side) 48" max (front)	Contract of	×	
The second	Emergency buttons 35" min	×		
1177	Location front on center opening/side on or front or side opening (fig 23 c and d)	×		
× 4.10.13	In-Car Position Indicator	X		
× 4.10.14	Emergency Communication		X	
	48 " max	3 11 11	X	
	Bell	X		
	Handset cord 29" min	×		N/A NO PHONE INSTAL
	Additional ICC requirements			
¥ 407 2 4	Hoistway Door horizontal opening	Х		
× 407.3.1	Buttons arranged in ascending order	×		
407 4 6 6 6	inductions arranged in ascending order	- A		
× 407.4.6.2.2 × 407.4.9.2.1	PI audible vocal over 200 fpm	X		N/A



Elevator: PENFIELD ELEV #3

Date ____7/1/08____

ADA ITEM #	DESCRIPTION	COMPLIANT ? YES	NO	NOTE
100000000000000000000000000000000000000	ADA STANDARDS 28CFR Part 36			HOLE
× 4.85.5(5)	Handrails 34" min 38" max to top	X		37"
X 4.10.1	Automatic Operation	×		240
	Self Leveling within 1/2" at rated/ unrated	v		
	load	х		1
X 4.10.3	Hall Call Buttons		X	
	42" Center Line		X	
	3/4" min raised or flush	×		
	visual call registered		X	
	No object projects more than 4" below call		-	
	station	×		1 1 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
X 4.10.4	Hall Lanterns		X	NONE
	Passing audible 1 up / 2 dwn			HONE
	72" min		-	
	Visual Element at least 2-1/2		-	
	Visible from hall call button		_	
× 4.10.5	Hoistway entrance Braille both jambs		v	- Augusta
-	60 in, center line		X	NONE
X 4.10.6	Door Protection	-	-	
4.10.0	to the second of	X		
X 4.10.7	20 sec delay min	X		
C SOME STATE	Hoistway Door Timing 5 sec. min	Х		
× 4.10.8	Car Door Delay 3 sec. min	X		
X 4.10.9	Floor Plan (Fig. 22)	×		EXISTING
	Floor plan exception 4.16(1)(k)(ii)(3)(c)(ii)			
	applies? (46" x 48" min or equivalent access provided)	×		
	Door Opening 36" min	x		
× 4.10.10	Floor Surfaces comply with 4.5	×		
	1/4" max level	X		
	carpeting secured			N/A
X 4.10.11	Lighting 5fc min.	X		EMERG. NOT TESTER
× 4.10.12	Car Controls		×	
	Buttons 3/4" min. raised or flush	×		
	Braille		×	
Ex Fil.	Visual Call Registered		×	
	Height 54" max. (side) 48" max (front)		×	
	Emergency buttons 35" min	×		
	Location front on center opening/ side on or			
	front or side opening (fig 23 c and d)	×		
X 4.10.13	In-Car Position Indicator	Х		
× 4.10.14	Emergency Communication		×	
	48 " max		х	
	Bell	x		
	Handset cord 29" min	X		N/A NO PHONE INSTALL
	LINE CONTROL OF THE C			The state of the s
	Additional ICC requirements			
W 400 0 4	The state of the s			
x 407.3.1	Hoistway Door horizontal opening	X		
X 407.3.1 407.4.6.2.2 407.4.9.2.1	Hoistway Door horizontal opening Buttons arranged in ascending order Pl audible vocal over 200 fpm	X X		N/A



Elevator: COOPER ELEV #4

Date ____7/1/08

	ADA STANDARDS 28CFR Part 36	COMPLIANT ? YES	NO	NOTE
X 4.85.5(5)	Handrails 34" min 38" max to top			
X 4.10.1			X	39"
A 4.10.1	Automatic Operation	X		
	Self Leveling within 1/2" at rated/ unrated load	x		
X 4.10.3	Hall Call Buttons			
X 4.70.3	42" Center Line		X	
	The state of the s		×	
	3/4" min raised or flush	X		
	visual call registered		X	
	No object projects more than 4" below call station			
X 4.10.4	Hall Lanterns	X		
N 10.4	Passing audible 1 up / 2 dwn		X	NONE
	72" min			
_				
	Visual Element at least 2-1/2			
¥ 4 40 F	Visible from hall call button			
X 4.10.5	Hoistway entrance Braille both jambs		×	NONE
	60 in. center line			
4.10.6	Door Protection			Safety edge exception
		X	4	4.1.6(1)(k)(ii)(3)(c)(i)
	20 sec delay min			
X 4.10.7	Hoistway Door Timing 5 sec. min	×		
× 4.10.8	Car Door Delay 3 sec. min	X		
X 4.10.9	Floor Plan (Fig. 22)	Х		EXISTING (36"D x 56"V
	Floor plan exception 4.1.6(1)(k)(ii)(3)(c)(ii)			(36"D x 56"W) Equivale
	applies? (48" x 48" mln or equivalent access	×		protection
	provided)			4.1.6(1)(k)(ii)(3)(c)(iii)
	Door Opening 36" min	×		
× 4.10.10	Floor Surfaces comply with 4.5	X		
	1/4" max level	×		
	carpeting secured			N/A
X 4.10.11	Lighting 5fc min.	×		EMERG. NOT TESTED
× 4.10.12	Car Controls		×	
	Buttons 3/4" min. raised or flush	×		a with
	Braille		×	
			-	
	Visual Call Registered		×	
100	Height 54" max. (side) 48" max (front)		×	
	Emergency buttons 35" mln		ж	
	Location front on center opening/ side on or			
	front or side opening (fig 23 c and d)	X		
X 4.10.13	In-Car Position Indicator	x		
¥ 4.10.14	Emergency Communication		X	
	48 " max		×	
	Bell	×		
	Handset cord 29" min	X	THE PERSON	N/A NO PHONE INSTALL
	Additional ICC requirements			
V 407 2 4		v	_	+
X 407.3.1	Hoistway Door horizontal opening	X		
407.4.6.2.2	Buttons arranged in ascending order PI audible vocal over 200 fpm	×	-	N/A
407.4.9.2.1				



ADA ITEM # DESCRIPTION COMPLIANT ? YES NO NOTE ADA STANDARDS 28CFR Part 36 X 4.85.5(5) Handralls 34" min 38" max to top 397 X 4.10.1 **Automatic Operation** Х Self Leveling within 1/2" at rated/ unrated X load X 4.10.3 Hall Call Buttons 42" Center Line 3/4" min raised or flush visual call registered No object projects more than 4" below call station X 4.10.4 Hall Lanterns X NONE Passing audible 1 up / 2 dwn 72" min Visual Element at least 2-1/2 Visible from hall call button X 4.10.5 Hoistway entrance Braille both jambs X NONE 60 In. center line 4.10.6 Door Protection 20 sec delay min CHECK ADJUSTMENT X 4.10.7 Hoistway Door Timing 5 sec. min CHECK ADJUSTMENT X X 4.10.8 Car Door Delay 3 sec. min CHECK ADJUSTMENT × 4.10.9 Floor Plan (Fig. 22) EXISTING X Floor plan exception 4.16(1)(k)(ii)(3)(c)(ii) applies? (48" x 48" min or equivalent access X provided) Door Opening 36" min X 4.10.10 Floor Surfaces comply with 4.5 × 1/4" max level carpeting secured EMERG. NOT TESTED X 4.10.11 Lighting 5fc min. X × 4.10.12 × **Car Controls** Buttons 3/4" min. raised or flush X Brailte × Visual Call Registered × × Height 54" max. (side) 48" max (front) X Emergency buttons 35" min Location front on center opening/ side on or X front or side opening (fig 23 c and d) × 4.10.13 In-Car Position Indicator X **Emergency Communication** × 4.10.14 48 " max Bell Handset cord 29" min N/A NO PHONE INSTALLED Additional ICC requirements X 407.3.1 Hoistway Door horizontal opening X × 407.4.6.2.2 Buttons arranged in ascending order N/A X 407.4.9.2.1 PI audible vocal over 200 fpm x



Elevator: HEWITT SRVC ELEV #58

ADA ITEM#	DESCRIPTION	COMPLIANT ? YES	NO	NOTE
¥ 4 0E =(=)	ADA STANDARDS 28CFR Part 36			
X 4.85.5(5)	Handralls 34" min 38" max to top	ورونيا والتراب	×	39"
X 4.10.1	Automatic Operation	×		
	Self Leveling within 1/2" at rated/ unrated load	×		
X 4.10.3	Hall Call Buttons		X	
	42" Center Line		×	
	3/4" min raised or flush	×		
	visual call registered	×		
	No object projects more than 4" below call			
	station	×	1	
X 4.10.4	Hall Lanterns		X	NONE
	Passing audible 1 up / 2 dwn			
	72" min			
	Visual Element at least 2-1/2			
	Visible from hall call button			
X 4.10.5	Hoistway entrance Braille both jambs		X.	NONE
	60 in. center line			
× 4.10.6	Door Protection	X		
	20 sec delay min		×	CHECK ADJUSTMEN
X 4.10.7	Hoistway Door Timing 5 sec. min		X	CHECK ADJUSTMEN
× 4.10.8	Car Door Delay 3 sec. min		X	CHECK ADJUSTMEN
X 4.10.9	Floor Plan (Fig. 22)	Х		EXISTING
	Floor plan exception 4.16(1)(k)(ii)(3)(c)(ii)	2		and the contract of
	applies? (48" x 48" min or equivalent access provided)	×		
	Door Opening 36" min	×		
X 4.10.10	Floor Surfaces comply with 4.5	×		
	1/4" max level	×		Part of the last o
	carpeting secured			N/A
X 4.10.11	Lighting 5fc min.	x		EMERG. NOT TESTEL
× 4.10.12	Car Controls		×	
	Buttons 3/4" min. raised or flush	ж		
	Braille		X	
	Visual Call Registered		×	
	Height 54" max. (side) 48" max (front)		×	
	Emergency buttons 35" min		×	
	Location front on center opening/ side on or	×		
V 4 40 42	front or side opening (fig 23 c and d)		-	
X 4.10.13	In-Car Position Indicator	X		
× 4.10.14	Emergency Communication		X	
	48 " max		×	
	Bell Wasterst 200 - In	X		BUG ALC DISCOURT STREET
	Handset cord 29" min	X	k	N/A NO PHONE INSTAL
	Additional ICC requirements			
		W		
X 407.3.1	Hoistway Door horizontal opening	X		
× 407.3.1 407.4.6.2.2 407.4.9.2.1	Hoistway Door horizontal opening Buttons arranged in ascending order PI audible vocal over 200 fpm	×		N/A



Elevator TYLER ELEV #6

Date 7/1/08

ADA ITEM#	ADA STANDARDS 28CFR Part 36	COMPLIANT ? YES	NO	NOTE
A DE E/EL				200
X 4.85.5(5)	Handrails 34" min 38" max to top		X	39"
X 4.10.1	Automatic Operation	Х		
	Self Leveling within 1/2" at rated/ unrated	X	1	
X 4,10.3	load		-	
X 4.10.3	Hall Call Buttons		X	
	42" Center Line		X	
	3/4" min raised or flush	×	-	
	visual call registered	×	-	
	No object projects more than 4" below call station	×	-	
X 4,10,4	Hall Lanterns	~	×	NONE
A 4.10.4	Passing audible 1 up / 2 dwn		^	NONE
	72" min			
	Visual Element at least 2-1/2		+	
	Visible from hall call button		-	
X 4,10,5	Hoistway entrance Braille both jambs		×	NONE
2 11.10.0	60 in. center line		^	HUNE
× 4.10.6	Door Protection	X	-	
4.10.0	20 sec delay min		X	CHECK ADJUSTMEN
X 4.10.7	Hoistway Door Timing 5 sec. min	×	-	GUERN MUJUSTMEN
× 4.10.8	Car Door Delay 3 sec. min	X		
X 4.10.9	Floor Plan (Fig. 22)	X		EXISTING
A 4.10.0	Floor plan exception 4.16(1)(k)(ii)(3)(c)(ii)	n	-	EXISTING
	applies? (48" x 48" min or equivalent access	×		
	provided)	^		
-	Door Opening 36" min	Х	_	
× 4,10.10	Floor Surfaces comply with 4.5	X		
4.10.10	1/4" max level	X		
	carpeting secured	1		N/A
× 4.10.11	Lighting 5fc mln.	X		EMERG. NOT TESTER
A 4010111	Eighting Sie milk	^		EMERG. NOT TESTEE
X 4.10.12	Car Controls		×	
-				
	Buttons 3/4" min. raised or flush	×		
	Braille		×	
	brame			
	Visual Call Registered		×	
	Height 54" max. (side) 48" max (front)		×	
	Emergency buttons 35" min		×	
- 1	Location front on center opening/ side on or		-	
	front on side opening (fig 23 c and d)	X	-	
× 4.10.13	In-Car Position Indicator	X		
× 4.10.14	Emergency Communication		×	
	48 " max		X	
	Bell	X		
	Handset cord 29" min	×		N/A NO PHONE INSTAL
	Additional ICC requirements			
x 407.3.1	Hoistway Door horizontal opening	X		
		X		
407.4.6.2.2	Buttons arranged in ascending order			
407.4.6.2.2	Buttons arranged in ascending order Pl audible vocal over 200 fpm	X	No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other pa	N/A

CAB RENOVATION UPGRADES:

The following opinion of probable costs for upgrades to the interior finishes of each of seven (7) elevators is based on standard finishes and assumes the retention of the existing elevator cab enclosure (shell). Interior finishes costs can vary widely based on the types and textures of finishes. In forming an opinion of the probable costs CNYEC has assumed the finishes and materials recently used at Seneca Hall will be similar to those used for the following cabs. Pictures of the typical finishes are included at the end of this section for general reference.

Notes:

OpCost for call fixtures have been included in this Opinion of Probable Cost, however the fixture costs were also included in the cost for controller upgrade. If controllers are replaced as part of an overall upgrade deduct the cost for fixtures as noted below.

OpCost for cab doors is not included in the probable cost. Cab doors can often be retained, however if the car doors are replaced a value is also noted below.

ELEVATOR #1: Sheldon

Existing Cab Finish: Applied Laminate Existing Call Fixtures: Stainless Steel

Existing Dimensions: 4-Stop (Front and Rear) 6'-8"W x 5-0"D x 8'-0"H

Opinion of Probable Cost: \$10,000 If controller is replaced deduct \$4,000 If car doors are replaced add \$6,000

ELEVATOR #2: Lanigan

Existing Cab Finish: Painted Steel Shell Existing Call Fixtures: Stainless Steel

Existing Dimensions: 3-stop 6'-8"W x 4'-2"D x 8'-0"H

Opinion of Probable Cost: \$16,000 If controller is replaced <u>deduct</u> \$3,000 If car doors are replaced <u>add</u> \$3,000



ELEVATOR #3: Penfield

Existing Cab Finish: Painted steel shell Existing Call Fixtures: Stainless steel

Existing Dimensions: 4-Stop 6'-8"W x 4-3"D x 8-0"H

Opinion of Probable Cost: \$16,000 If controller is replaced deduct \$4,000 If car doors are replaced add \$3,000

ELEVATOR #4: Cooper

Existing Cab Finish: Textured stainless steel

Existing Call Fixtures: Stainless steel

Existing Dimensions: 2-stop 4'-8"W x 3-0"D x 7'-6"H

Opinion of Probable Cost: \$10,000 If controller is replaced <u>deduct</u> \$3,000 If car doors are replaced <u>add</u> \$3,000

ELEVATOR #5A: Hewitt Passenger

Existing Cab Finish: Painted steel shell Existing Call Fixtures: Stainless steel

Existing Dimensions: 3-stop 6'-8"W x 4'-1"D x 8'-0"H

Opinion of Probable Cost: \$16,000 If controller is replaced <u>deduct</u> \$3,000 If car doors are replaced <u>add</u> \$3,000

ELEVATOR # 5B: Hewitt Service

Existing Cab Finish: Painted steel shell Existing Call Fixtures: Stainless steel

Existing Dimensions: 3-stop 6'-8"W x 7'-6"D x 8'-0"H

Opinion of Probable Cost: \$17,000 If controller is replaced deduct \$3,000 If car doors are replaced add \$3,000



ELEVATOR #6: Tyler

Existing Cab Finish: Painted steel finish Existing Call Fixtures: Stainless steel

Existing Dimensions: 3-stop 6'-8"W x 7-8"D x 8'-0"H

Opinion of Probable Cost: \$17,000 If controller is replaced <u>deduct</u> \$3,000 If car doors are replaced <u>add</u> \$3,000



PICTURES FROM SENECA HALL

















126 North Salina St. Suite 305 Syracuse, NY 13202 Ph (315) 425-0428 Fax (315) 425-1232 www.enyelevatorconsultants.com Copyright © 2008







