

## SUNY Oswego Facilities Services Monthly Project Update

December, 2016

| Project #                   | 100049  |                     |
|-----------------------------|---|---------------------|
| Project Name                | Wilber Hall - Interior Demolition & Abatement   |                     |
| Project Scope               | Scope includes the removal of asbestos material and existing building elements that are no longer needed.  Expansion of the existing sprinkler system into the one-story portion of the building will provide code-compliant coverage of those spaces.  All work will be in preparation for SOE-III renovations.  |                     |
| Project Phase               | C3 - Construction   |                     |
| Current Project Coordinator | Mark Fuller   |                     |
| Consultants                 | Adirondack Operations   | IPD Engineering     |
| Contractors                 | Massa Construction  | Simplex Grinnell LP |
| Project Update              | Sprinkler Expansion - Simplexgrinnell has submitted as-built drawings, waiting on approval prior to painting and finishes. One portion of their sprinkler head install is contingent on the demolition and abatement project taking down a tent in the lower level of Wilber. The work involving the install of the sprinkler heads will not be completed until the demolition and abatement work is completed.  Demolition and Abatement - Due to the general contractor Massa Construction's inability to have the demolition and abatement contract work finished by their new subcontractor Flower City Monitor Services in a timely manner the Campus has asked the general contractor if they are in a position to continue and deliver the finished abatement scope. The general contractor has assessed the situation and found that it is not feasible to pursue finishing the contract work. The general contractor has supplied a letter stating that they have "exhausted financial resources well beyond those dedicated to this project." The abatement subcontractor is continuing the abatement of the walls within the work area, they will proceed with cleaning the ceiling (mostly done other than where walls were demoed) and walls. This will leave the flooring on the 2nd & 3rd levels and stair tower to be backed out of the contract. |                     |

|   | Project Start Date        | 06/06/2014   |
|---|---------------------------|--------------|
|   | Project Finish Date       | 04/04/2018   |
| Project Schedule                            | Planning Start Date       | 06/06/2014   |
|   | Planning Finish Date      | 07/21/2014   |
|   | Design Start Date         | 03/06/2015   |
|   | Design Finish Date        | 10/02/2015   |
|   | Construction Start Date*  | 05/02/2016   |
|   | Construction Finish Date* | 04/04/2018   |
|   | Equipment Start Date      |              |
| *Construction Dates Include Warranty Period | Equipment Finish Date     |              |
|   |                           |              |
| Project Costs                               | Projected Budget          | \$ 1,000,750 |
|   | Projected Costs           | \$ 789,856   |
|   | Projected Budget Variance | \$ 210,894   |